

12/21/59

December 21, 1959

Pioneer Bore
Inspection Findings

A. Julian

A.G. Johnson

Geology of Pioneer Bore.

At your request an inspection of the Pioneer Bore was made December 11th and December 15th, 1959 by our engineering geologist, Stanley Mitchell and all assisted by Ralph Rhodes, a geologist attached to the Design Section. The purpose of this inspection was to make a geologic log of the Pioneer Bore and to establish limits for the need of concrete lining.

The Pioneer Bore was excavated last summer through a steep sided ridge located two miles east of Idaho Springs. The bore is approximately 800 feet long and 8 by 7 feet in cross-section.

The bedrock through which it was cut consists of schist and gneiss of the Idaho Springs Formation. The U.S. Geological Survey has classified the rock as a quartz monzonite gneiss of Pre-Cambrian age. The foliation or bedding of the gneiss parallels closely the alignment of the tunnel and dips 40 to 70 degrees to the north.

At the west portal the formation has been folded and faulted. The rock has been sheared and crushed to some extent and shows considerable alteration by weathering processes. The foliation shows overturning to the south opposite the proposed right lane tunnel. Thin veins of pyrite (FeS₂) were noted along the fault both in the bore and west of the portal. Water follows up along the fault and comes out into the bore in several places. The water was tested by the Chemistry Section and the tests indicate very little acidity or presence of sulfates. However, this does not preclude the possibility that the water may become acid and charged with sulfates at a future time, particularly if its circulation is restricted. The presence of pyrites suggests this possibility.

The effects of faulting are evident in the Pioneer Bore between Stations 173+10 to 174+90. Timber sets have been necessary in several places to help stabilize the roof. Some of the rocks tend to expand and slab off.

cc: Benagh
Hiles - Stearns
Koppert
Rausohl
S. Mitchell
Project File
att /1/

L. Miller
December 21, 1959
Page 7

Several layers of biotite schist, along with fault gouge and scapage, indicate location of fault zones. The rocks in this area show jointing at approx. 90° right angles to the foliation, and this jointing still further weakens the rock.

East of Station 173+00 the bedrock grades is harder, less weathered and appears to be reasonably sound, except for joints which tend to break the formation into disconformal slabs. Most of the joints appear to be tight except near the west portal. Here the formations show the effect of weathering and more open joints back approximately 40 feet from the portal.

The location of the faulted zones, weathering, the strike and dip of the foliation and joints have been plotted on the attached Geologic Log both in plan and in sections. This information can assist the engineer in determining the probable limits for concrete lining in both the left and right lane tunnels. The suggested limits shown for concrete lining are based upon rock conditions found in the Pioneer Mine. It is possible that the rock structure in the right lane tunnel might not be found to exist exactly as projected on the Geologic Log. However, we feel the rock conditions between Stations 173+20 and 175+20 may be similar to that found in the Pioneer Mine and may need to be concrete lined. The exact limits can be better determined at the time of excavation.

The original determination of the width of the pillar between the left and right lane tunnels was predicated upon the existence of relatively solid rock. However, the excavation made for the west portals and Pioneer Mine indicates a zone of relatively weak rock between Stations 173 and 175. The structure and character of the rock between these stations suggest the need for a re-evaluation of the pillar width, or consideration be given to extra support for the tunnel linings. We suggest that an expert in mining engineering be consulted on this matter before final plans and specifications are finalized.

C. E. Strata
Assistant Chief Engineer

R. O. Hanson
Staff Materials Engineer

RM:lg