

Tran, An

From: Coffrin, William
Sent: Thursday, January 20, 2011 7:41 AM
To: Hoefler, Gerald
Cc: Harris, Timothy; Wright, Chad; Bennett, Charles; Heller, Gerhard; Greer, Matt; Hutton, Pamela; McDaniel, Scott; Leonard, Mark; Deland, John; Nord, Mark; Tatalaski, Tom; Mondragon, Karen; Anderson, Jeffrey; Bridge Records
Subject: H-17-M - Spalled CBC Wall (2nd Notice)
Attachments: H17M Spalling on divider wall as deep as four inches.jpg; Region 2 Essential Repairs Tracking Spreadsheet.xls

MEMORANDUM

DEPARTMENT OF TRANSPORTATION
Staff Bridge Branch
4201 E. Arkansas Avenue, Room 107
Denver, Colorado 80222
(303) 757-9309 FAX (303) 757-9197

DATE: January 20, 2011
To: Gerald Hoefler – Region 2 Maintenance Super.
Jeff Anderson
FROM: Jeff Anderson – Staff Bridge
SUBJECT: H-17-M – Spalled CBC Wall (2nd Notice)

The following bridge is recommended for repairs as recently discovered by the bridge inspection program:

Structure No. H-17-M: I 25 over a Draw at Milepoint 156.936.

The divider wall is badly spalled, as deep as four inches for a length of fifty feet. The spalling continues below the groundline.

It is our office's recommendation that these items be repaired. Should you have any questions regarding the work, please contact John Deland at (303) 512-4076. Thank you!

Cc: Tim Harris – Region 2 Director
Chad Wright – Region 2 Bridge Maint.
Chuck Bennett – Region 2 Maint.
Gary Heller – Region 2 Maint.
Matt Greer – FHWA
Pam Hutton – Chief Engineer
Scott McDaniel – Staff Branches
Mark Leonard – Staff Bridge
Deland/Nord – Staff Bridge

Tatalaski/Mondragon – Bridge Inspections
Bridge Records

