



I17DG (Spalling below Girder 1Q at Abutment 1).JPG

Taken: 2012/09/24 3:02

Posted: 2012/09/25

File Size: 2756274

\\public\bridge common\briar please use this\gold\damage\



I17DG Asph. above Abut 5 outside lane and shldr is cracked moderately and has potholes.JPG

Taken: 2006/08/2310:20

Posted: 2006/11/07

File Size: 1114948

I17DG Old Utility box in deck bottom bay 3P has hole thru deck and is causing deter of deck bottom.JPG

Taken: 2006/08/2311:32

Posted: 2007/04/25

File Size: 656740



Inspector photos_7_.JPG

Taken: 2004/12/01 12:03
Posted: 2009/01/09
File Size: 160944
e:\web\folders\I-17-DG\

Inspector photos_6_.JPG

Taken: 2004/12/01 12:03
Posted: 2009/01/09
File Size: 163206
e:\web\folders\I-17-DG\




Inspector photos_5_.JPG

Taken: 2004/12/01 12:03
Posted: 2009/01/09
File Size: 171393
e:\web\folders\I-17-DG\

Inspector photos_4_.JPG

Taken: 2004/11/26 9:18
Posted: 2009/01/09
File Size: 118665
e:\web\folders\I-17-DG\




Inspector photos.JPG

Taken: 2004/11/26 9:17
Posted: 2009/01/09
File Size: 98061
e:\web\folders\I-17-DG\

DTD archives_2_.JPG

Taken: 2004/11/23 8:36
Posted: 2009/01/09
File Size: 15741
e:\web\folders\I-17-DG\



DTD archives.JPG

Taken: 2004/11/23 8:36
Posted: 2009/01/09
File Size: 20130
e:\web\folders\I-17-DG\