



**I17DG (Spalling below Girder 1Q at Abutment 1).JPG**

**Taken:** 2012/09/24 3:02

**Posted:** 2012/09/25

**File Size:** 2756274

\\public\bridge common\briar please use this\gold\damage\



**I17DG Asph. above Abut 5 outside lane and shldr is cracked moderately and has potholes.JPG**

**Taken:** 2006/08/2310:20

**Posted:** 2006/11/07

**File Size:** 1114948

**I17DG Old Utility box in deck bottom bay 3P has hole thru deck and is causing deter of deck bottom.JPG**

**Taken:** 2006/08/2311:32

**Posted:** 2007/04/25

**File Size:** 656740



**Inspector photos\_7\_.JPG**

**Taken:** 2004/12/01 12:03  
**Posted:** 2009/01/09  
**File Size:** 160944  
e:\web\folders\I-17-DG\

**Inspector photos\_6\_.JPG**

**Taken:** 2004/12/01 12:03  
**Posted:** 2009/01/09  
**File Size:** 163206  
e:\web\folders\I-17-DG\




**Inspector photos\_5\_.JPG**

**Taken:** 2004/12/01 12:03  
**Posted:** 2009/01/09  
**File Size:** 171393  
e:\web\folders\I-17-DG\

**Inspector photos\_4\_.JPG**

**Taken:** 2004/11/26 9:18  
**Posted:** 2009/01/09  
**File Size:** 118665  
e:\web\folders\I-17-DG\




**Inspector photos.JPG**

**Taken:** 2004/11/26 9:17  
**Posted:** 2009/01/09  
**File Size:** 98061  
e:\web\folders\I-17-DG\

**DTD archives\_2\_.JPG**

**Taken:** 2004/11/23 8:36  
**Posted:** 2009/01/09  
**File Size:** 15741  
e:\web\folders\I-17-DG\



**DTD archives.JPG**

**Taken:** 2004/11/23 8:36

**Posted:** 2009/01/09

**File Size:** 20130

e:\web\folders\I-17-DG\