COLORADO DEPARTMENT OF TRANSPORTATION
REGION 4
10601 West 10th Street
Greeley, CO 80634

Summary Observations

An on-site ADA survey was conducted November 25, 2016, by Patrick Going, ADA Consultant. All observations are based on the *2010 ADA Standards for Accessible Design*. These Standards may be found at www.access-board.gov.

CDOT Region 4 is located in a new building shared with the Colorado State Patrol. Most of the building is for 'employees only' which are covered under Title I of the Americans with Disabilities Act (ADA). Only those areas were observed where the public may visit.

Parking

There are 28 visitor parking spaces with 6 designated accessible. There are no designated "Van" accessible spaces although there are 8 foot access aisles to accommodate this identification.

Path-of-Travel

The route to the main entrance is accessible. Power assist is available at both sets of doors.

Rest Rooms

The public restrooms meet all the ADA Standards with the exception of the door opening pressures being 11 lbs.

Conference Rooms

There is one conference room available to the public. It is fully accessible with the exception the opening door pressure is 11 lbs.

ADA Compliance*
*Based on *2010 ADA Standards for Accessible Design*

Excellent **Excellent** Moderate **Moderate** Poor **Poor**

Parking	Route to Building	Restrooms	Conference Room
Excellent	Excellent	Excellent	Excellent
28 visitor parking spaces with 6 marked accessible.	Paved surface and accessible routes are ADA Compliant	ADA compliant with exception door opening pressure is 11 lbs.	ADA compliant with exception door opening pressure is 11 lbs.

Recommendations	
Description	**Priority**
Add a'van' sign to two of the vertical posts designating accessible parking spaces.	Immediate
Reduce interior opening door pressure to 5 lbs at the two public restrooms and conference room	Immediate
Relocate or add restroom signs next to door - see picture below	Soon

RESERVED
PARKING
Recommend adding 'van' sign to these two spaces
8' access aisle allows 'van' designation

Accessible path-of-travel

Power assist entrance door
TRASH
MIXED RECYCLABLES
Recommend moving bin 2' left for clear floor space at door activation pad


EXIT
FIRE
Good

Better to put sign on wall on latch side of door
X
MEN 108


Good sign - but technically should be on adjacent wall
X
WOMEN 109

Perfect!

Perfect!


Good accessible interior route