MicroStation

Placing Curved Leader Lines

Did you know that you can place curved leader lines with the Place Note command? Open the Place Note dialog box, set the Location to Manual and the Leader Type to Curve. You can then place as many curves in your leader line as you wish. You will also need to remember to change the Location setting back to Automatic when you want to place a regular dimension.