COLORADO DEPARTMENT OF TRANSPORTATION

JOB SAFETY ANALYSIS

Activity Name: Hveem stabilometer Test on HMA Samples	**Activity Number:** CP-L5106

Activity Description & Purpose:
Perform stability test on samples.

Date Prepared: January 24, 2008				**PPE Required**
Typical Equipment		**Typical Crew Size:**	**Typical Material**	Safety glasses/Hardtoe boots/Heat resistant gloves/Heat resistant apron
Description	Class Code	(Crew sizes may vary due to different conditions throughout the state).	Description / Class Code	
See associated test procedure		1	See associated test procedure	

Sequence of Job Tasks	Potential Hazards	Safe Job Procedures	Never
1-Place sample into 140 degree oven.	1-Burns	1-Wear all personal protective equipment.	handle hot materials without gloves
2-Place sample in stabilometer.	1-Foot injury	1-Wear all personal protective equipment.	drop the stabilometer
3-Place Stabilometer unit into press.			

Distribution:
Insert to CP-L Manual at start of CP-L5106

CDOT Form # 1370 05/06