Region 2 Major Structure 5-Year Asset Management Plan

Status Date: 6/19/2015

TSIOUVARAS SIMMONS HOLDERNESS CONSULTING ENGINEERS

COLORADO Department of Transportation

	Project Information						Structure Information																				Scope and Prioritization					Funding		
	Project Type	Project SA	Project Number Project Description	Resident Engineer	Designer	Ad Date	Structure	Year Built	NHS	Route Carried	Feature Intersected	Ref Point	Latitude	Longitude	County	ADT	% Truck Traffic	Structure Type	NBI Rating Deck	NBI Rating Super	NBI Rating Sub	Sufficiency Rating	Functional Status	Deck Area	Years Life Added	BPM Eligible (Deck/Joint)	Scour Critical	Essential Repair	Repair Priority	Bridge Repairs	FY2015 Repair	FY2015 Scour	FY2015 BPM
																														Sub Total	$7,218,565	$0	$4,200,000
																														Total	$11,418,565		
																														Budget	$10,493,130		
																														% of Budget	109%		
2015			Cimarron				-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-						$5,246,565		
	Repair	20253	Rainbow Falls Bridge Rehab. BR M850-024 20253	David Watt	CDOT	TBD	I-17-AI	1932		024E	FOUNTAIN CREEK	0.1460	38.8698	-104.926	EL PASO	1900		CA	4	4	4	66.6	SD	7559	20	Deck			3		$200,000		
	Surface Treatment	19652	Overlay I-25 Ludlow North to Apishipa River MP 26.6 to 32.5	Joe DeHeart	CDOT	Dec-14	O-18-BX	1959		County Road 44	I 25 ML	0.0000	37.3396	-104.568	LAS ANIMAS	182		CSGC	6	7	7	83.6	0	5567	20	Deck			0		$82,000		
							O-18-CC	1969	NHS	025A	DEL AGUA CANYON	27.4590	37.3482	-104.572	LAS ANIMAS	5900	20%	CSG	7	7	6	85.6	0	5849					0				
							O-18-BZ	1959	NHS	025A	DEL AGUA CANYON	27.4600	37.3480	-104.573	LAS ANIMAS	5900	20%	CSG	7	6	6	75.8	FO	4633	20	Deck			0				
							O-18-BI	1958		Cnty Rd to Aguilar	I 25 ML	0.0000	37.3831	-104.603	LAS ANIMAS	481		CIC	4	4	5	55.8	SD	8278	20	Deck		y	4				
		19654	Overlay SH47 Junction I-25 to East of Troy MP 0.35 to 2.928	Joe DeHeart	CDOT	Dec-14	K-18-EL	1968		Bonfort Blvd	SH 47 ML	1.8650	38.3039	-104.581	PUEBLO	9736		CPG	4	6	6	91	SD	9295	15	Both			2		$1,400,000		
							K-18-FO	1984	NHS	047A	FOUNTAIN CREEK	0.5020	38.3074	-104.604	PUEBLO	16550	4%	CPGC	7	8	8	92.2	0	25095					0				
							K-18-EY	1977		Jerry Murphy Rd	SH 47 ML	0.0000	38.3078	-104.598	PUEBLO	25285		CSGC	7	8	7	93	0	13319					0				
							K-18-FN	1984	NHS	047A	CITY ST, UP RR	0.1540	38.3073	-104.610	PUEBLO	16100	4%	CPGC	7	8	8	88.1	FO	11871	15	Joints		g	0				
							K-18-GC	1999	NHS	047A	CITY ST, UP RR	0.1550	38.3075	-104.610	PUEBLO	16550	4%	CBGC	8	8	8	78.2	FO	9458	15	Joints			0				
							K-18-EJ	1968	NHS	047A	FOUNTAIN CREEK	0.5030	38.3076	-104.604	PUEBLO	16550	4%	CPGC	6	7	7	86.3	0	30318	15	Joints			0				
							K-18-GA	1996	NHS	047A	TROY AVE	2.4110	38.2998	-104.572	PUEBLO	6700	7%	CBGP	8	8	7	100	0	6380	15	Joints			0				
							K-18-EX	1978	NHS	047A	TROY AVE	2.4120	38.2999	-104.572	PUEBLO	6700	7%	CBGP	6	6	5	89	0	7053	15	Joints			0				
		20172	Overlay SH 85 Junction I-25 through Fountain to B Street MP 128 to 131.2 and 135.4 to 137.1	Dan Hunt	CDOT	Jan-15	J-18-M	1930	NHS	085A	FOUNTAIN CREEK	128.1400	38.6773	-104.705	EL PASO	9200	6%	SDG	5	5	5	58.6	0	17034	20	Deck			0		$290,000		
							J-18-B	1930	NHS	085A	DRAW	130.7420	38.7123	-104.713	EL PASO	12200	3%	CI	5	5	7	56.1	FO	632	20	Deck			0				
							I-17-R	1965	NHS	085A	FOUNTAIN CREEK	136.6910	38.7766	-104.779	EL PASO	10500	3%	WGC	5	5	6	64.2	0	10120	20	Deck	High	g	2				
							I-17-CO	1956	NHS	085A	I 25 ML	136.9010	38.7761	-104.783	EL PASO	10500	3%	CI	5	5	5	53.6	0	7169	20	Deck			0				
		19653	Overlay SH45 Junction I-25 to Thatcher Blvd MP 0 to 4.65	Joe DeHeart	CDOT	Jun-15	L-18-BA	1963	NHS	045A	I 25 ML	0.0010	38.2170	-104.621	PUEBLO	17200	4%	CSGC	6	7	6	83.6	0	15192					0				
		18842	Overlay I25 Academy North MP 153.7 to 155.5	Dan Hunt	CDOT	TBD	H-17-I	1958	NHS	025A	MONUMENT CREEK BRANCH	155.0370	39.0139	-104.827	EL PASO	81000		CBC	N	N	N	93.3	0	0					0				
							H-17-AG	1953	NHS	025A	MONUMENT CREEK BRANCH	154.8920	39.0137	-104.826	EL PASO	81000		CBC	N	N	N	93.3	0	0			Medium		1				
		20225	Overlay SH16A Between Mesa Ridge PKWY and Fountain Mesa RD MP 2.3 to 2.8	-		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
		NA	Overlay US50B Washington to JCT US 287 (Lamar) MP 434.8 to 435.3	-		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
		NA	Overlay US287A Cedar to JCT US 50 (Lamar) MP 77 to 77.6	-		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
		NA	Overlay US160C KIM - East and West MP 405 to 425.69	-		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
	BPM	19942	Bridge Preventative Maintenance Project set prepared for 2014. BR 0252-437	Mark Andrew		Jan-15	J-18-Q	2002	NHS	085A	I25 ML	128.0010	38.6730	-104.709	EL PASO	9500	6%	CPGC	7	8	7	95.1	FO	16762	15	Both			0				$4,200,000
							J-18-BM	2009	NHS	016A	I 25 ML	0.0010	38.7245	-104.733	EL PASO	21400		CPGC	8	8	8	99	0	25565	20	Deck			0				
							J-18-BN	2009	NHS	016A	FOUNTAIN CREEK	0.1200	38.7259	-104.730	EL PASO	20700	5%	CPGC	8	8	8	85.9	0	48537	15	Both			0				
							J-18-BO	2009	NHS	016A	CREWS GULCH	0.2980	38.7258	-104.728	EL PASO	21500		CPGC	9	9	9	95.4	0	8264	20	Deck			0				
							I-17-GN	1969	NHS	024A	WILLIAMS CANYON, RDWY	297.7060	38.8635	-104.917	EL PASO	27400	4%	WGCK	7	6	7	91.2	0	24074	15	Both			0				
							I-17-NU	2005	NHS	021B	PINE CREEK	151.8000	38.8917	-104.769	EL PASO	9700		CPG	8	8	8	64.7	0	6117	20	Deck			0				
							I-17-MJ	2005	NHS	021B	KETTLE CREEK	153.8100	38.9758	-104.752	EL PASO	9700	5%	WGCK	8	8	8	93.7	0	32043	20	Deck			0				

Region 2 Major Structure 5-Year Asset Management Plan

Status Date: 6/19/2015

TSIOUVARAS SIMMONS HOLDERNESS CONSULTING ENGINEERS

COLORADO Department of Transportation

Project Type	Project SA	Project Number Project Description	Resident Engineer	Designer	Ad Date	Structure	Year Built	NHS	Route Carried	Feature Intersected	Ref Point	Latitude	Longitude	County	ADT	% Truck Traffic	Structure Type	NBI Rating Deck	NBI Rating Super	NBI Rating Sub	Sufficiency Rating	Functional Status	Deck Area	Years Life Added	BPM Eligible (Deck/Joint)	Scour Critical	Essential Repair	Repair Priority	Bridge Repairs	FY2016 Repair	FY2016 Scour	FY2016 BPM
																													Sub Total	$7,089,436	$194,000	$3,257,000
																													Total	$10,540,436		
																													Budget	$8,288,872		
																													% of Budget	127%		
2016		Cimarron				-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-						$4,144,436		
Repair	19425	BR 231A-001 Redecking (Plans are complete)	Craig Wieden	CDOT	TBD	K-19-A	1965		231A	ARKANSAS RIVER	1.4450	38.2667	-104.458	PUEBLO	1700		WGC	4	6	7	78.6	SD	16851	20	Deck	Medium		2		$2,400,000		
Surface Treatment	20487	Overlay SH71 Arkansas River North MP 18.9 to 27	Dan Dahlke	CDOT	Feb-15	L-22-L	1934		071C	ARKANSAS RIVER	19.0020	38.1060	-103.748	OTERO	1600		CI	5	6	4	48.8	SD	13001	15	Both			1	To be replaced			
						L-22-K	1934		071C	FT LYON CANAL	19.2560	38.1095	-103.748	OTERO	1600		STG	5	4	6	37.6	SD	2687	20	Deck			1	Recently Replaced			
						L-22-J	1934		071C	LAKE CANAL	19.2960	38.1101	-103.748	OTERO	1600		CI	7	6	7	65.6	0	1271	20	Deck			0				$17,000
						L-22-BK	1965		071C	LAKE MEREDITH CANAL	21.9420	38.1479	-103.748	CROWLEY	1600		CBC	N	N	N	98.6	0	0					0				
						L-22-G	1966		071C	BOB CREEK CANAL	24.3880	38.1819	-103.748	CROWLEY	1400		CS	8	8	8	86.9	0	2021	20	Deck			0				$98,000
	20752	Overlay SH24A Chaffee Park/Parc CL (Trout CR Pass) East MP 225.55 to 234 and Overlay US285D Antero JCT North MP 161.8 to 162	Mark Andrew	CDOT	TBD	I-13-G	1937		024A	DRAW	227.0950	38.9246	-105.957	PARK	1400		TTS	6	5	6	71.5	0	2058					0				
						I-13-I	1937		024A	AGATE CREEK	234.5930	38.9935	-105.862	PARK	1400		TTS	7	6	7	85.6	0	725			High		1			$194,000	
						I-13-H	1937		024A	DRAW	229.4310	38.9348	-105.919	PARK	1400		TTS	6	6	6	85.3	0	2069					0				
	20519	Overlay Apishipa North I-25A MP 32.5 to 39	Joe DeHeart	CDOT	Winter '15	O-18-CD	1969	NHS	025A	APISHAPA RIVER	32.7980	37.4114	-104.627	LAS ANIMAS	5900		CSG	6	6	5	77.3	0	8859	15	Joints			1	Concrete Patching	$125,000		$53,000
						O-18-BY	1959	NHS	025A	APISHAPA RIVER	32.7990	37.4110	-104.628	LAS ANIMAS	5900		CSG	6	6	6	80.7	0	8772	15	Both			0	Concrete Patching	$42,000		$244,000
						O-18-BH	1959	NHS	025A	I 25 BUSS RT	34.0830	37.4273	-104.639	LAS ANIMAS	5900		CSG	7	7	7	90.3	FO	3551	20	Deck			0				$79,000
						O-18-BE	1959	NHS	025A	I 25 BUSS RT	34.0840	37.4271	-104.640	LAS ANIMAS	5900		CSG	7	7	6	90.3	FO	3552	20	Deck			0				$49,000
						O-18-BD	1959	NHS	025A	DRAW	35.2570	37.4347	-104.644	LAS ANIMAS	4550		CSG	6	7	6	82.5	0	3554	20	Deck			0	Concrete Patching	$28,000		$107,000
						O-18-CA	1969	NHS	025A	DRAW	35.2560	37.4348	-104.644	LAS ANIMAS	4550		CSG	7	7	7	96.3	0	3570					0	Plug Joints	$31,000		
						O-18-AX	1959	NHS	025A	RUGBY ARROYO	36.4510	37.4580	-104.656	LAS ANIMAS	4550		CSG	7	6	5	79.8	0	3570	20	Deck			0	Plug Joints+Conc Patch	$118,000		$49,000
						O-18-AG	1969	NHS	025A	RUGBY ARROYO	36.4500	37.4579	-104.656	LAS ANIMAS	4550		CSG	7	7	6	96.6	0	3602					0	Concrete Patching	$1,000		
						O-18-BN	1959		0	I 25 ML	0.0000	37.4710	-104.662	LAS ANIMAS	6		CSGC	6	6	7	87.8	0	17623	20	Deck			0				
						O-18-CB	1969	NHS	025A	SALADO CREEK	38.3150	37.4845	-104.666	LAS ANIMAS	4550		CSG	7	7	6	96.5	0	4692	15	Joints			0				$77,000
						O-18-BU	1959	NHS	025A	SALADO CREEK	38.3160	37.4845	-104.667	LAS ANIMAS	4550		CSG	6	7	6	92.3	0	4690	20	Deck			0				$101,000
	19134	Overlay SH47A East end of PCCP to Junction US 50B MP 4 to 4.6 and Overlay SH96A Arkansas River to US 50B through Pueblo MP 55.4 to 58.81	Joe DeHeart	HDR/CDOT	Winter '15	K-18-FA	1979	NHS	047A	11TH ST	4.3510	38.2784	-104.556	PUEBLO	10100		CPG	6	8	7	86.3	0	5286					0				
						K-18-CR	1959	NHS	025A	SH 96 ML	98.7210	38.2707	-104.605	PUEBLO	55000		CSGC	7	7	7	75	0	20025					0				
						K-18-BT	1954	NHS	096A	UP RR, FOUNTAIN CRK	56.3410	38.2708	-104.601	PUEBLO	19300		CIC	4	6	6	62.7	SD	26879	15	Both		o	4	Replace Light Pole	$5,000		$1,202,000
						K-18-AD	1936	NHS	096A	BIG DRY CREEK	58.3080	38.2718	-104.566	PUEBLO	8100		TTS	6	5	6	82.5	0	4827					0				
						K-18-FD	1979	NHS	047A	US 50 ML	4.6340	38.2749	-104.558	PUEBLO	10100		CPGC	7	8	8	76	0	8595					0	Flowfill	$1,000		
						K-18-J	1958	NHS	050B	I 25 ML	316.0100	38.2878	-104.606	PUEBLO	32600		CSG	6	5	5	71.1	0	11538	15	Both		o	4	Substructure Repair	$194,000		
	19751	Overlay SH50A EB Only Purcell BLVD to Wills BLVD MP 309.4 to 312.8	Dan Dahlke	FHU	Nov-14	K-18-CW	1975	NHS	050A	DRY CREEK	312.4910	38.3128	-104.652	PUEBLO	19850		CSGC	8	8	8	97.8	0	7808					0				
						K-18-CZ	1975	NHS	050A	WILLIAMS CREEK	312.4330	38.3134	-104.657	PUEBLO	19850		CBC	N	N	N	83.9	0	0					0				
	19015	Overlay SH94A Ellicott East to El Paso/Lincoln CL MP 17.2 to 35.01	David Watt	CDOT	Winter '15	I-19-AJ	1966		094A	BLACK SQUIRREL CREEK	18.4850	38.8385	-104.361	EL PASO	2400		CSGC	5	6	8	79.4	0	4406	15	Both		g	1				$203,000
						I-19-B	1968		094A	BIG SPRING CREEK	19.5750	38.8387	-104.342	EL PASO	2400		CSGP	6	6	6	80.6	0	2351	15	Both			0				$116,000
						I-20-AM	1983		094A	DRAW	25.2160	38.8393	-104.237	EL PASO	2000		CBC	N	N	N	99.4	0	1740					0				
						I-20-AO	1983		094A	DRAW	25.9640	38.8393	-104.223	EL PASO	2000		CBC	N	N	N	99.4	0	1759					0				
						I-20-AN	1983		094A	DRAW	26.3880	38.8393	-104.215	EL PASO	1300		CBC	N	N	N	99.4	0	2905					0				
						I-20-H	1972		094A	DRAW	32.7600	38.8400	-104.098	EL PASO	1100		CBC	N	N	N	98.7	0	0					0				
						I-20-Y	1971		094A	STEEL FORK	34.7660	38.8401	-104.061	EL PASO	910		CBC	N	N	N	96.7	0	0					0				
	20467	Overlay SH24E MP 0 to 0.7, 1.4 to 2.4, 0 to 0.4	Dan Hunt		TBD	I-17-GH	1969	NHS	024A	FOUNTAIN CREEK SR	298.9460	38.8585	-104.898	EL PASO	3900		CPG	4	7	6	78.2	SD	3040		Both			1				$100,000
	20225	Overlay SH16A Mesa Ridge PKWY North to SH21 MP 1.34 to 3.12	Mark Andrew		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
	20225	Overlay SH21A End of SH16 to Bradley MP 131.8 to 134.5	Mark Andrew		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
	NA	Overlay US287A Cedar St South MP 76.0 to 77	-		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
BPM	20809	I25 and Rockrimmon	David Watt		TBD	I-17-NK	2008	NHS	025A	ROCKRIMMON BLVD.	147.2740	38.9327	-104.813	EL PASO	49300		CBGP	7	7	7	94.3	0	7556	15	Deck		y	2				$167,000
						I-17-NL	2008	NHS	025A	ROCKRIMMON BLVD.	147.2750	38.9327	-104.812	EL PASO	49300		CBGP	8	8	8	94.3	0	7556	15	Deck			0				$167,000
						I-17-NQ	2008	NHS	025A	NEVADA AVE.	148.1200	38.9157	-104.817	EL PASO	49300		CBGP	8	7	8	95.7	0	9696	20	Both			0				$214,000
						I-17-NR	2008	NHS	025A	NEVADA AVE.	148.1100	38.9155	-104.817	EL PASO	49300		CBGP	7	8	8	90.5	0	9694	20	Both			0				$214,000

Region 2 Major Structure 5-Year Asset Management Plan

Status Date: 6/19/2015

TSIOUVARAS SIMMONS HOLDERNESS CONSULTING ENGINEERS

COLORADO Department of Transportation

Project Type	Project SA	Project Number Project Description	Resident Engineer	Designer	Ad Date	Structure	Year Built	NHS	Route Carried	Feature Intersected	Ref Point	Latitude	Longitude	County	ADT	% Truck Traffic	Structure Type	NBI Rating Deck	NBI Rating Super	NBI Rating Sub	Sufficiency Rating	Functional Status	Deck Area	Years Life Added	BPM Eligible (Deck/Joint)	Scour Critical	Essential Repair	Repair Priority	Bridge Repairs	FY2017 Repair	FY2017 Scour	FY2017 BPM
																													Sub Total	$4,046,109	$0	$6,234,000
																													Total	$10,280,109		
																													Budget	$7,692,218		
																													% of Budget	134%		
2017		Cimarron				-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-						$3,846,109		
Surface Treatment	TBD	Overlay I25A ST Fund Advance for Cimarron MP 140.2 to 141.3	David Watt		TBD	I-17-EI	1959	NHS	025A	DRAW	140.7120	38.8226	-104.836	EL PASO	87400		CBC	N	N	N	70	0	0					0	Part of Cimarron Project			
						I-17-DG	1959	NHS	025A	US 24 ML, FOUNTAIN CRK	141.1090	38.8281	-104.835	EL PASO	87400		CPG	5	5	5	55.2	FO	21755	15	Joints			0	Part of Cimarron Project			
	20951	Overlay SH67D North of Woodland Park MP 79.5 to 91.7	Dan Hunt		TBD	H-16-L	1939		067D	DRAW	80.0610	39.0323	-105.079	TELLER	3300		TTS	6	6	6	62.7	FO	1020					0	Substructure Repair	$10,000		
						H-16-M	1939		067D	LONG GULCH CREEK	82.0920	39.0602	-105.092	TELLER	1800		TTS	6	7	6	72.8	0	1247					0	Substructure Repair	$10,000		
						H-16-I	2000		067D	TROUT CREEK	83.7630	39.0834	-105.097	TELLER	1800		CBGP	8	8	8	97.1	0	3618					0				
	20956	Overlay SH115A (Old 085K - Nevada) S of Cheyenne Rd to Arvada St MP 46.1 to 47.4	Dan Hunt		TBD	I-17-GO	1971	NHS	115A	US 85 ML	45.9890	38.7972	-104.822	EL PASO	32500		CBGC	7	6	6	99.8	0	22421					0	Substructure Repair	$50,000		
	TBD	Overlay US285D Fairplay North MP 180.9 to 190	Dan Hunt		TBD	H-13-A	1937	NHS	285D	MIDDLE FK S.PLATTE RVR	182.8200	39.2194	-105.994	PARK	5800		CI	5	6	5	58.8	FO	1859	20	Deck			0	Substructure Repair	$10,000		$57,000
						G-13-G	1937	NHS	285D	TROUT CREEK	188.9960	39.2773	-105.926	PARK	5100		CBC	N	N	N	69	0	0					0				
	TBD	Overlay US350A E and W of Las Animas-Otero CL MP 33.3 to 46.7	Dan Patrick		TBD	N-21-E	1935		350A	TAYLOR ARROYO	40.5970	37.6762	-103.982	OTERO	430		CI	5	6	6	54.2	0	2519	20	Deck			0	Substructure Repair	$10,000		$6,000
						N-21-B	1936		350A	IRON SPRINGS ARROYO	43.0300	37.6929	-103.946	OTERO	430		TTS	6	5	5	75.7	0	4768					0	Substructure Repair	$20,000		
						N-21-G	1936		350A	IRON SPRINGS ARROYO	45.9760	37.7127	-103.899	OTERO	430		CI	6	6	7	71.7	0	3338	20	Deck			0				$106,000
						N-21-H	1936		350A	DRAW	46.1050	37.7137	-103.896	OTERO	430		TTS	6	6	6	85.1	0	710					0	Substructure Repair	$10,000		
						N-20-I	1987		350A	DRAW	33.9270	37.5963	-104.033	LAS ANIMAS	430		CBC	N	N	N	99.9	0	0					0				
	TBD	Overlay SH45A East of Thatcher BLVD to US50 MP 4.8 to 8.73	Dan Dahlke		TBD	K-18-EP	1973	NHS	045A	RR, ARKANSAS RIVER	5.3840	38.2688	-104.662	PUEBLO	29700		WGCK	7	7	7	66	0	22557	15	Joints		b	0				$62,000
						K-18-EU	1974	NHS	045A	UP RR	6.3490	38.2818	-104.663	PUEBLO	14350		CICK	7	7	6	98	0	7700	15	Joints			0	Substructure Repair	$20,000		$47,000
						K-18-EV	1982	NHS	045A	UP RR	6.3500	38.2819	-104.663	PUEBLO	14350		CICK	7	8	6	99.3	0	7342					0	Substructure Repair	$20,000		
	20929	Overlay US24G MLK Bypass NB & SB Ramps MP 303.4 to 304.1	David Watt	CDOT	TBD	I-17-JA	1990	NHS	024G	I 25 ML, FOUNTAIN CRK	303.6270	38.8082	-104.806	EL PASO	34500		CPGC	6	8	7	89	0	89763	15	Joints	Low	o	0				$31,000
						I-17-JL	1990	NHS	024G	CITY ST,UP RR,DITCH	304.0580	38.8088	-104.798	EL PASO	18350		CPGC	6	8	7	97.2	0	23844	15	Joints			0				
						I-17-JC	1990	NHS	024G	CITY ST,UP RR,DITCH	304.0570	38.8086	-104.798	EL PASO	18350		CPGC	7	8	7	96.2	0	27551					0				
	20778	Overlay SH96C Haswell to Eads MP 143.7 to 165.9	Brian Long		TBD	K-25-N	1989		096C	DRAW	153.6170	38.5017	-103.012	KIOWA	450		CBC	N	N	N	99.9	0	1359					0				
						K-25-C	1936		096C	DRAW	158.8210	38.4920	-102.917	KIOWA	450		TTS	6	6	6	79.5	0	999					0	Substructure Repair	$10,000		
						K-25-M	1987		096C	KIOWA CREEK	165.7540	38.4780	-102.789	KIOWA	760		CBC	N	N	N	100	0	2367					0				
	TBD	Overlay 167A MP 0 to 4.9	TBD		TBD	L-20-F	1958		167A	ARKANSAS RIVER	0.9600	38.1409	-104.023	OTERO	750		CIC	5	6	6	82.2	0	11784		Both			0	Substructure Repair	$30,000		$455,000
	20911	Overlay SH24G WB Constitution to Garret MP 314.5 to 318.4	Mark Andrew		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
	20929	Overlay I25A MLK Bypass North MP 139 to 139.7	David Watt		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
	NA	Overlay US287A North of College RD South MP 74.4 to 76.05	-		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
BPM	20809	Rockrimmon Part 2	David Watt	TSH	TBD	I-17-NG	2008	NHS	025A	MARK DABLING BLVD/UPRR	147.4050	38.9098	-104.824	EL PASO	94300		CBGCP	7	8	8	88	0	17295	20	Both			0				$383,000
						I-17-NJ	2008	NHS	025A	MARK DABLING/UPRR	147.3950	38.9113	-104.823	EL PASO	5455		CBGCP	7	6	8	87.5	0	20039	20	Deck		g	1				$443,000
						I-17-NH	2008	NHS	025A	MARK DABLING/UPRR	147.4020	38.9109	-104.823	EL PASO	45250		CBGCP	7	7	8	95.9	0	34543	20	Deck			0				$764,000
						I-17-NI	2008	NHS	025A	MARK DABLING/UPRR	147.4000	38.9104	-104.823	EL PASO	45250		CBGCP	7	7	7	90.7	0	34543	15	Both			0				$764,000
						I-17-NN	2008	NHS	025A	MONUMENT CREEK	148.0000	38.9145	-104.819	EL PASO	49300		CBGCP	7	7	8	95.7	0	32233					0				$713,000
						I-17-NO	2008	NHS	025A	MONUMENT CREEK	147.9600	38.9142	-104.818	EL PASO	49300		CBGCP	8	8	8	90.5	0	32240					0				$713,000
	20948	BPM Project 2017	Dan Hunt	TSH	TBD	H-17-BB	2004	NHS	025A	DIRTY WOMAN CREEK R	160.7510	39.0901	-104.864	EL PASO	65700		WGC	8	8	8	93.1	0	22999	15	Both			0				$337,000
						H-17-CZ	2004		105A	I 25 ML	5.2100	39.0923	-104.863	EL PASO	12500		CPGC	7	8	8	87.5	0	13389	20	Deck			0				$236,000
						H-17-DA	2004		105A	DIRTY WOMAN CREEK	4.8940	39.0931	-104.858	EL PASO	260		WG	7	7	7	100	0	5682	20	Deck			0				$377,000
						I-18-BE	1994	NHS	024G	EAST FORK SAND CREEK	309.6940	38.8222	-104.726	EL PASO	37200		CPG	7	8	8	98.3	0	10804	15	Both			0				$580,000
						K-18-FB	2005	NHS	025A	EAGLE RIDGE BLVD.	102.1390	38.3205	-104.616	PUEBLO	28700		CPGC	8	8	8	97	0	22000	20	Deck			0				$160,000

Region 2 Major Structure 5-Year Asset Management Plan

Status Date: 6/19/2015

TSIOUVARAS SIMMONS HOLDERNESS CONSULTING ENGINEERS

COLORADO Department of Transportation

Project Type	Project SA	Project Number Project Description	Resident Engineer	Designer	Ad Date	Structure	Year Built	NHS	Route Carried	Feature Intersected	Ref Point	Latitude	Longitude	County	ADT	% Truck Traffic	Structure Type	NBI Rating Deck	NBI Rating Super	NBI Rating Sub	Sufficiency Rating	Functional Status	Deck Area	Years Life Added	BPM Eligible (Deck/Joint)	Scour Critical	Essential Repair	Repair Priority	Bridge Repairs	FY2018 Repair	FY2018 Scour	FY2018 BPM
																													Sub Total	$5,653,000	$0	$6,124,000
																													Total	$11,777,000		
																													Budget	$5,396,601		
																													% of Budget	218%		
2018 Repair	TBD	Bridge Deck Replacement Project	TBD		TBD	M-21-C	1937		350A	HOE RANCH ARROYO	50.5820	37.7590	-103.839	OTERO	430		CI	4	5	6	50.6	SD	3778		Deck			1.0	Deck Replacement	$454,000		
	TBD	Bridge Deck Replacement Project	TBD		TBD	M-22-U	1935		350A	OTERO DITCH	69.8170	37.9548	-103.590	OTERO	560		CI	4	5	6	74.7	SD	1319		Deck		g	2.0	Deck Replacement	$159,000		
	TBD	Bridge Repair Project	TBD		TBD	L-23-B	1956		194A	FORT LYON CANAL	9.4500	38.0732	-103.399	BENT	1100		CSG	7	5	4	55.5	SD	2637		Deck			1.0	Substructure Repair	$20,000		
	TBD	Bridge Repair Project	TBD		TBD	K-18-U	1929	NHS	025A	DRAW	111.9230	38.4582	-104.608	PUEBLO	14800		CI	5	4	6	56.7	SD	1715		Deck			1.0	Girder Repair	$50,000		
	TBD	Bridge Repair Project	TBD		TBD	I-17-GR	1971	NHS	025A	ACADEMY BLVD	135.2340	38.7649	-104.776	EL PASO	26550		WGCK	6	3	7	53.9	SD	12807		Both			1.0	Girder Repair	$50,000		
	TBD	Bridge Repair Project	TBD		TBD	N-17-D	1933		025C	CUCHARAS RIVER	1.0240	37.6187	-104.778	HUERFANO	2300		CI	5	5	5	77.6	0	5466		Both		y	2.0	Sub Repair/Corbel	$50,000		
	TBD	Bridge Replacement Project	TBD		TBD	M-22-Z	1939		010A	CROOKED ARROYO	69.6750	37.9822	-103.599	OTERO	910		CI	5	6	5	42.6	0	2786		Both	Medium		1.0	Bridge Replacement	$1,500,000		
	20119	Bridge Replacement Project	TBD		TBD	M-16-P	1948		069A	MILLIKEN ARROYO	28.6030	37.8021	-105.215	HUERFANO	490		TTS	5	6	3	39.4	SD	2253				y	3.0	Bridge Replacement	$3,000,000		
	20344	Bridge Repair Project	TBD		TBD	K-18-BL	1972	NHS	050A	US 50 ML	312.7960	38.3119	-104.647	PUEBLO	36600		WG	8	5	6	NA	NA	2649							$200,000		
Surface Treatment	20964	Overlay I-25A Trinidad South MP 7.5 to 12.9	Joe DeHeart		TBD	P-18-BN	1967	NHS	025A	COUNTY ROAD, DRAW	7.5270	37.0861	-104.522	LAS ANIMAS	4650		CSGC	7	7	7	86.4	0	5929	20	Deck			0				$81,000
						P-18-BO	1967	NHS	025A	COUNTY ROAD, DRAW	7.5280	37.0860	-104.522	LAS ANIMAS	4650		CSGC	7	6	6	86.8	0	5702	20	Deck			0	Substructure Repair	$20,000		$78,000
						P-18-BS	1968		0	I 25 ML	0.0000	37.1343	-104.521	LAS ANIMAS	9499		CSGC	5	6	7	67.7	FO	5320	15	Both			0				$340,000
						P-18-E	1951	NHS	025A	ARROYO	12.2370	37.1523	-104.520	LAS ANIMAS	13800		CAC	N	N	N	82.2	0	0					0				
	20756	Overlay US 50B Fowler to Manzanola MP 352 to 359 and SH167A Fowler North and South MP 0 to 4.86	Dan Dahlke		TBD	L-21-D	2006	NHS	050B	HUNGERFORD HOLLOW	352.4850	38.1276	-103.994	OTERO	4200		CBC	N	N	N	99.8	0	1596					0				
						L-21-A	1947	NHS	050B	OTERO CANAL	354.3240	38.1229	-103.961	OTERO	4700		CRF	7	7	7	81.1	0	800	20	Deck			0				$11,000
						L-21-DA	1997	NHS	050B	APISHAPA RIVER	355.0340	38.1210	-103.947	OTERO	2400		CPGC	8	8	7	86.2	0	14204					0				
						L-21-G	1957	NHS	050B	APISHAPA RIVER	355.0240	38.1209	-103.947	OTERO	2400		RG	6	5	4	50.8	SD	9775	15	Joints			1	Substructure Repair	$60,000		$236,000
						L-21-I	1957	NHS	050B	OTERO CANAL	355.1190	38.1208	-103.946	OTERO	2400		CSG	7	7	7	91.4	0	1393					0				
						L-21-DC	1998	NHS	050B	OTERO CANAL	355.1200	38.1210	-103.946	OTERO	2400		CDTPG	8	7	8	99.9	0	1633					0				
						L-21-DB	1997	NHS	050B	SMITH HOLLOW	358.3780	38.1149	-103.888	OTERO	4700		CPG	8	8	8	99.8	0	5145					0				
						L-20-F	1958		167A	ARKANSAS RIVER	0.9600	38.1409	-104.023	OTERO	750		CIC	5	6	6	82.2	0	11784					0	Substructure Repair	$30,000		
	20910	Overlay US 160C Junction 389 East MP 382.97 to 405	Brian Long		TBD	P-21-G	1958		160C	VACHITA CREEK	385.6960	37.1647	-103.827	LAS ANIMAS	180		SSM	5	6	6	88.8	0	624			Low		0	Substructure Repair	$10,000		
						P-22-D	1934		160C	CHACUACO CREEK	390.2270	37.1681	-103.748	LAS ANIMAS	190		CI	5	6	5	69.1	0	2749	20	Deck	Medium		1	Substructure Repair	$20,000		$84,000
						P-22-C	1934		160C	ARCHULETA CREEK	393.4120	37.1891	-103.694	LAS ANIMAS	190		CI	5	6	7	82.9	0	1618	20	Deck			0				$78,000
						P-22-B	1934		160C	Draw	396.2320	37.2055	-103.651	LAS ANIMAS	200		CS	7	7	7	88.3	0	550	20	Deck			0				$8,000
						P-22-A	1934		160C	TOBE CREEK	396.8840	37.2097	-103.640	LAS ANIMAS	190		CI	5	6	6	85.3	0	1549	20	Deck	Medium		1	Substructure Repair	$10,000		$47,000
	TBD	Overlay US 287A Spreading Antlers GC South MP 73 to 74.4	TBD		TBD	L-26-I	1947	NHS	287A	WILLOW CREEK	74.1260	38.0373	-102.615	PROWERS	3000		CI	6	7	6	77.9	0	3718	15	Both			0	Substructure Repair	$10,000		$80,000
	TBD	Overlay SH9A JCT US50 North MP 0 to 18.17	TBD		TBD	J-15-A	1967		009A	CURRANT CREEK	3.1400	38.5284	-105.388	FREMONT	1500		CSGC	6	7	6	74	0	2938		Deck			0	Substructure Repair	$10,000		$63,000
						J-15-F	2012		009A	CURRANT CREEK	11.3460	38.6177	-105.446	FREMONT	750		CBGCP	8	8	8	54.4	0	5289					0				
	TBD	Overlay SH69A Huerfano/Custer CL North MP 42.3 to 50.1	TBD		TBD	L-15-R	2012		069A	ANTELOPE CREEK	49.5490	38.0295	-105.388	CUSTER	560		CBC	N	N	N	40.5	0						0				
	20750	Overlay SH50C Santa Fe Ave/Fourth St to Baxter Rd MP 0 to 7.39	Dan Dahlke		TBD	K-18-AY	1958	NHS	025A	US 50 BUS. RTE.	97.6710	38.2563	-104.607	PUEBLO	30650		CIC	6	7	6	60.5	FO	9599	20	Deck		g	1	Part of Ilex Project			
						K-18-AX	1958	NHS	025A	US 50 BUS. RTE.	97.6700	38.2565	-104.607	PUEBLO	30650		CIC	5	7	5	49.7	FO	7182	20	Deck			1	Part of Ilex Project			
						K-18-FF	1978	NHS	050C	ARKANSAS RIVER	1.1340	38.2545	-104.607	PUEBLO	10050		WGCK	7	8	7	98.9	0	10636	15	Joints			0				$263,000
						K-18-R	1924	NHS	050C	ARKANSAS RIVER	1.1360	38.2545	-104.607	PUEBLO	10050		STT	4	4	5	47.2	SD	7577	20	Deck			3	Part of Ilex Project			
						L-18-BE	2003	NHS	050C	CF&I RR, CF RR	2.2120	38.2466	-104.591	PUEBLO	23000		CBGP	8	8	7	94.8	0	10390					0				
						L-18-BD	2003	NHS	050C	SH 227 ML, SALT CREEK	2.3080	38.2461	-104.589	PUEBLO	23000		CPGC	7	8	7	87.5	0	32223					0				
	20725	Overlay US285D Antero JCT North MP 162 to 171.8	Mark Andrew		NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-								
BPM	20916	2018 BPM Bridges	Mark Andrew		TBD	I-17-CD	2002	NHS	025A	WOODMEN ROAD	148.7980	38.9329	-104.812	EL PASO	49300		CBGC	7	8	7	94.1	0	13539		Both			0.0				$676,000
						I-17-CE	2002	NHS	025A	WOODMEN ROAD	148.7990	38.9330	-104.813	EL PASO	49300		CBGCP	7	7	7	98	0	13541		Both			0.0				$676,000
						I-17-LR	2000	NHS	025A	Uintah Street	142.8010	38.8507	-104.832	EL PASO	46500		CBGP	7	7	7	98	0	12420		Both			0.0				$660,000
						I-17-O	1960	NHS	025A	PINE CREEK SR	149.2480	38.9387	-104.813	EL PASO	8310		CIC	5	6	5	35.8	FO	5280		Both		g	1.0				$383,000
						I-17-OO	2008	NHS	025A	COLORADO AVE, SPRUCE ST	141.4570	38.8328	-104.833	EL PASO	45300		CBGCP	7	7	7	95.9	0	14459		Deck			0.0				$320,000
						I-17-OP	2008	NHS	025A	COLORADO AVE, SPRUCE ST	141.4880	38.8327	-104.833	EL PASO	45300		CBGCP	7	7	7	93.8	0	12667		Both			0.0				$280,000
	TBD	2018 BPM Bridges	TBD		TBD	N-26-O	1976	NHS	287A	SOUTH HORSE CREEK	38.3250	37.5219	-102.620	BACA	3100		CIC	5	7	7	82.1	0	7630		Deck			0.0				$297,000
						N-26-P	1976	NHS	287A	HORSE CREEK	39.9240	37.5452	-102.620	BACA	3100		CIC	7	7	7	83.3	0	6237		Deck			0.0				$138,000
						N-26-Q	1975	NHS	287A	TRIB HORSE CREEK	40.0770	37.5474	-102.620	BACA	3100		CIC	6	7	7	84.5	0	5926		Deck			0.0				$177,000
						N-26-R	1976	NHS	287A	SAND CREEK	42.4480	37.5818	-102.621	BACA	2300		CIC	6	7	7	86.1	0	6865		Deck			0.0				$205,000
						N-26-T	1992	NHS	287A	TWO BUTTES CREEK	46.5050	37.6406	-102.620	BACA	2300		CPGC	6	8	7	88.4	0	17248		Deck			0.0				$514,000
						O-26-A	1935	NHS	287A	BEAR CREEK	32.2100	37.4333	-102.617	BACA	3100		CICK	7	7	7	85.4	0	8012		Deck			0.0				$177,000
						O-26-P	1989	NHS	287A	DRAW	21.1250	37.2736	-102.615	BACA	2600		CBGCP	7	7	7	97.6	0	6736		Deck			0.0				$252,000

Region 2 Major Structure 5-Year Asset Management Plan

Status Date: 6/19/2015

TSIOUVARAS SIMMONS HOLDERNESS CONSULTING ENGINEERS

COLORADO Department of Transportation

	Project Information						Structure Information																				Scope and Prioritization					Funding		
	Project Type	Project SA	Project Number Project Description	Resident Engineer	Designer	Ad Date	Structure	Year Built	NHS	Route Carried	Feature Intersected	Ref Point	Latitude	Longitude	County	ADT	% Truck Traffic	Structure Type	NBI Rating Deck	NBI Rating Super	NBI Rating Sub	Sufficiency Rating	Functional Status	Deck Area	Years Life Added	BPM Eligible (Deck/Joint)	Scour Critical	Essential Repair	Repair Priority	Bridge Repairs	FY2019 Repair	FY2019 Scour	FY2019 BPM
																														Sub Total	$150,000	$3,525,839	$1,028,000
																														Total	$4,703,839		
																														Budget	$1,036,660		
																														% of Budget	454%		
2019	High Priority Scour		Vertical sheetpile drop structure at culvert outlet				I-18-BG	1995	NHS	024G	SAND CREEK	309.8140	38.8302	-104.722	EL PASO	38700		CBC	N	N	N	67.3	SD	0			High		2.5			$286,000	
2019	High Priority Scour		Pier caisson underpinning and left abutment caissons				I-17-EG	1964	NHS	024A	FOUNTAIN CREEK	302.0880	38.8397	-104.858	EL PASO	19700		CSG	7	7	6	78.8	FO	2173		Deck	High		1.0			$435,000	
2019	High Priority Scour		Pier caisson underpinning and left abutment caissons				I-17-EQ	1964	NHS	024A	FOUNTAIN CREEK	302.0870	38.8396	-104.858	EL PASO	19700		CSG	6	7	6	78.8	FO	2174		Deck	High		1.0			$435,000	
2019	High Priority Scour		Riprap protection at Pier 2. Soldier pile and precast panel wall at Pier 3				N-17-BN	1967	NHS	025A	CO RD 640, BUTTE CREEK	58.7150	37.7450	-104.833	HUERFANO	5850		WGC	6	6	4	49.3	SD	5810		Deck	High		3.0			$332,000	
2019	High Priority Scour		Grouted bolder drop structure and grouted riprap/boulders				P-17-A	1936		012A	ZARACILLO CANYON	53.7200	37.1235	-104.763	LAS ANIMAS	980		CSG	5	6	6	77.6	0	3580		Deck	High		1.0			$943,000	
2019	High Priority Scour		Concrete apron with a sheetpile cutoff wall				P-17-L	1925		012A	DRAW	51.4570	37.1298	-104.802	LAS ANIMAS	980		CAC	N	N	N	83.1	0	778			High		0.0			$231,000	
2019	Culvert	20859	STA 094A-034	Dan Dahlke		TBD	I-18-AX	1980		094A	DRAW	4.0780	38.8389	-104.627	EL PASO	10900		CBC	N	N	N	84.4	0	2099				g	0.0			$663,839	
2019	Culvert	TBD	TBD	TBD		TBD	I-15-T	1937		024A	DRAW	271.6910	38.9480	-105.258	TELLER	5000		CBC	N	N	N	55.5	SD						1.5			$200,000	
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-F	2000	NHS	050A	DRAW	229.5910	38.4752	-105.884	FREMONT	4300		CBC	N	N	N	84.2	0	0					0				
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-G	1934	NHS	050A	SPRING CREEK	230.0730	38.4722	-105.878	FREMONT	4300		CA	6	6	6	66.2	0	2069	20	Deck			0		$10,000		$44,000
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-R	1934	NHS	050A	HOWARD CREEK	233.7290	38.4435	-105.839	FREMONT	2800		CI	7	7	6	73.3	0	953	20	Deck			0		$10,000		$13,000
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-L	1934	NHS	050A	DRAW	233.8600	38.4418	-105.838	FREMONT	2800		CI	6	6	6	72	0	1249	20	Deck			0		$10,000		$27,000
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-N	1934	NHS	050A	CHERRY CREEK	235.5850	38.4297	-105.817	FREMONT	2800		CI	6	7	6	72	0	1559	20	Deck			0		$10,000		$33,000
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-T	1934	NHS	050A	STOUT CREEK	235.8230	38.4286	-105.813	FREMONT	2800		CI	6	6	6	60.2	0	960	20	Deck			0		$10,000		$21,000
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-Q	1934	NHS	050A	DRAW	237.3710	38.4129	-105.792	FREMONT	2800		CI	7	7	6	56.4	0	1560	20	Deck			0		$10,000		$21,000
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-M	1934	NHS	050A	DRAW	237.7020	38.4094	-105.787	FREMONT	2800		CI	5	6	6	48.4	0	1559	20	Deck			0		$10,000		$48,000
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-O	1934	NHS	050A	DRAW	238.6760	38.3975	-105.778	FREMONT	2800		TTS	6	6	7	60.2	0	2044					0				
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-P	1934	NHS	050A	DRAW	238.9690	38.3934	-105.777	FREMONT	2800		TTS	6	6	6	60	0	2043					0		$10,000		
2019	Surface Treatment	TBD	Overlay US 50A East of Salida East MP 227 to 240.2	TBD		TBD	K-13-H	1936	NHS	050A	DRAW	239.8510	38.3836	-105.768	FREMONT	2800		CBC	N	N	N	99.9	0	0					0				
2019	Surface Treatment	TBD	Overlay I 25A MP 128 to 135	TBD		TBD	J-18-AK	1956	NHS	025A	DRAW	128.3130	38.6795	-104.713	EL PASO	20400		CICK	7	7	7	97	0	5127					0				
2019	Surface Treatment	TBD	Overlay I 25A MP 128 to 135	TBD		TBD	J-18-AL	1956	NHS	025A	DRAW	128.3090	38.6793	-104.714	EL PASO	20400		CICK	7	8	7	97	0	5127					0				
2019	Surface Treatment	TBD	Overlay I 25A MP 128 to 135	TBD		TBD	J-18-BD	1956	NHS	025A	CLOVER DITCH	131.1560	38.7187	-104.728	EL PASO	20400		CSG	6	7	6	84.7	0	3950		Deck			0		$20,000		$85,000
2019	Surface Treatment	TBD	Overlay I 25A MP 128 to 135	TBD		TBD	J-18-BA	1956	NHS	025A	CLOVER DITCH	131.1570	38.7186	-104.729	EL PASO	20400		CSG	6	6	6	83.2	0	4989		Deck			0		$30,000		$107,000
2019	Surface Treatment	TBD	Overlay I 25A MP 128 to 135	TBD		TBD	J-18-BM	2009	NHS	016A	I 25 ML	0.0010	38.7245	-104.733	EL PASO	21400		CPGC	8	8	8	99	0	25565		Deck			0				
2019	Surface Treatment	TBD	SH 194A Otero/Bent County Line to US 50 MP 10.13 to 20.33	TBD		TBD	L-23-AH	1956		194A	FORT LYON CANAL	11.2220	38.0847	-103.379	BENT	1100		CSG	7	7	5	79.6	0	2023	20	Deck			0		$20,000		$28,000
2019	Surface Treatment	TBD	SH 194A Otero/Bent County Line to US 50 MP 10.13 to 20.33	TBD		TBD	L-23-AI	1956		194A	HORSE CREEK	12.7810	38.0847	-103.353	BENT	1100		CBC	N	N	N	96.2	0	732					0				
2019	Surface Treatment	TBD	SH 194A Otero/Bent County Line to US 50 MP 10.13 to 20.33	TBD		TBD	L-24-B	1959	NHS	050B	SH 194 ML	400.0740	38.0849	-103.220	BENT	2150		CSGC	5	6	7	78.9	0	3812	20	Deck		g	1				$117,000
2019	Surface Treatment	TBD	SH 194A Otero/Bent County Line to US 50 MP 10.13 to 20.33	TBD		TBD	L-24-Z	1974	NHS	050B	SH 194 ML	400.0750	38.0849	-103.220	BENT	2150		CSGC	6	6	7	97.3	0	5341					0				
2019	BPM	TBD	2018 BPM Bridges	TBD		TBD	K-18-AI	1950		096A	BESSEMER DITCH	51.7740	38.2588	-104.679	PUEBLO	3800		CS	7	7	7	95.3	0	2256		Deck			0.0				$50,000
2019	BPM	TBD	2018 BPM Bridges	TBD		TBD	K-26-J	2003	NHS	287B	Lone Wolf Canal	100.5290	38.3332	-102.720	KIOWA	2500		CPG	8	7	7	62.2	FO	6091		Both			0.0				$135,000
2019	BPM	TBD	2018 BPM Bridges	TBD		TBD	L-21-CW	1969	NHS	050B	BNSF RR	360.9800	38.1026	-103.844	OTERO	2650		WGCK	5	7	7	97.3	0	6570		Both		g	1.0				$299,000