

Staff Bridge Branch 2829 W. Howard Place, 3rd Floor Denver, CO 80204

MFMORANDUM

DATE: Friday, June 19, 2020

TO: All Bridge Worksheet Users

FROM: Michael Collins, Staff Bridge Branch Manager

SUBJECT: CDOT Bridge Worksheets Updates

The following worksheets have been updated and are now available. Individual changes are identified in the following paragraphs.

These updates, and all of the worksheets, are available through the CDOT bridge web page. http://www.codot.gov/library/bridge/design-standards

B-INDEX-2: Updated revisions log and revision table cells for this submittal.

B-606-10MASH: Revised Baseplate Thickness to match Crash Test and updated quantities, Added note that changes must be approved by Staff Bridge.

B-606-10MASHA: Revised Baseplate Thickness to match Crash Test and updated quantities, Added note that changes must be approved by Staff Bridge.

B-606-10MASHA-S: Revised Baseplate Thickness to match Crash Test and updated quantities, Added note that changes must be approved by Staff Bridge.

B-618-CBT1: Revised reinforcing to Welded Wire Reinforcing to match industry practice and revised and added notes to Detailer/Designer.

B-618-CBT2: Deleted information for CBT30 & CBT36 and added CBT37.5 to match current industry capabilities.

Use of these worksheets is mandatory on all projects.

Please review and become familiar with these revisions. If you have any questions or recommendations for improvement to the worksheets, please contact:

Hoang.bui@state.co.us (303) 512-4075

MPC/hhb

Distribution via e-mail:

Jared Esquibel Staff Bridge Employees Structural Consultants

