



CSG-F.85-08.23 Typical debonding failure in plug joint.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 358680
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Transverse cracking with impending potholes in asphalt at west.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 336104
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Transverse crack with impending potholes at A5 in westbound travel lane.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 340261
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Spalling with exposed corroded rebar at south edge of deck at P4.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 240041
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Spall with exposed rebar in median.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 342798
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Settled and cracked curb and gutter at southwest.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 296469
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Scupper not sealed properly allowing seepage onto super and substructure at east end of P2.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 195328
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Ruts in westbound travel lane.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 348701
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Roadway looking west.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 202907
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Roadway looking east.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 175519
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Potholes in westbound travel lane.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 330432
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Horizontal cracks in abutment at A5.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 174172
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Delamination at end of pier cap at P2.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 212390
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Cracks with efflorescence in soffit in Span 4.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 161878
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Cracks and spalls with exposed rebar beneath light blister.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 187975
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Cracking, spalling, exposed rebar, and active leakage below median at P2.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 206120
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Cracking with efflorescence in south face of Column 2F.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 169453
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Cracking and delamination with efflorescence and rust staining at A1 at southwest.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 238591
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Chloride staining, efflorescence, exposed rebar, and rust staining at median at P4.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 211120
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Chloride staining and efflorescence full length of median.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 191049
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Channel looking upstream.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 241494
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Channel looking downstream.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 343203
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 Areas of saturation and efflorescence in deck soffit below face of curb.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 192063
e:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



CSG-F.85-08.23 Active leaking underneath bridge at median.JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 266248
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.23 .JPG

Taken: 2012/12/03 3:33
Posted: 2012/12/04
File Size: 317829
e:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4907.JPG

Taken: 2010/04/16 2:51
Posted: 2010/10/21
File Size: 490302
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4928.JPG

Taken: 2010/04/13 10:23
Posted: 2010/10/21
File Size: 695005
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4927.JPG

Taken: 2010/04/1310:22
Posted: 2010/10/21
File Size: 673479
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4926.JPG

Taken: 2010/04/1310:09
Posted: 2010/10/21
File Size: 669031
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4925.JPG

Taken: 2010/04/13 10:09
Posted: 2010/10/21
File Size: 676054
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4923.JPG

Taken: 2010/04/13 10:09
Posted: 2010/10/21
File Size: 660484
F:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



DSCF4922.JPG

Taken: 2010/04/13 10:07
Posted: 2010/10/21
File Size: 691914
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4921.JPG

Taken: 2010/04/13 9:58
Posted: 2010/10/21
File Size: 666957
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4919.JPG

Taken: 2010/04/13 9:58
Posted: 2010/10/21
File Size: 684247
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4917.JPG

Taken: 2010/04/13 9:57
Posted: 2010/10/21
File Size: 695652
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4916.JPG

Taken: 2010/04/13 9:56
Posted: 2010/10/21
File Size: 669840
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4915.JPG

Taken: 2010/04/13 9:54
Posted: 2010/10/21
File Size: 703222
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4914.JPG

Taken: 2010/04/13 9:53
Posted: 2010/10/21
File Size: 695462
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4913.JPG

Taken: 2010/04/13 9:52
Posted: 2010/10/21
File Size: 692516
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4912.JPG

Taken: 2010/04/13 9:32
Posted: 2010/10/21
File Size: 671136
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4911.JPG

Taken: 2010/04/13 9:31
Posted: 2010/10/21
File Size: 671235
F:\FOR DAVID TO UPDATE



WEB\CSG-F.85-08.23\



DSCF4910.JPG

Taken: 2010/04/13 9:31
Posted: 2010/10/21
File Size: 694324
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

DSCF4909.JPG

Taken: 2010/04/13 9:31
Posted: 2010/10/21
File Size: 690875
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\



DSCF4908.JPG

Taken: 2010/04/13 9:29
Posted: 2010/10/21
File Size: 659617
F:\FOR DAVID TO UPDATE
WEB\CSG-F.85-08.23\

CSG-F.85-08.2312.jpg

Taken: 2008/05/09 11:49
Posted: 2010/09/07
File Size: 647730
refile



CSG-F.85-08.2311.jpg

Taken: 2008/05/09 11:47
Posted: 2010/09/07
File Size: 703930
refile

CSG-F.85-08.2310.JPG

Taken: 2008/03/28 9:43
Posted: 2010/09/07
File Size: 579840
refile



CSG-F.85-08.230Z.JPG

Taken: 2008/03/28 9:42
Posted: 2010/09/07
File Size: 590439
refile

CSG-F.85-08.230Y.JPG

Taken: 2008/03/28 9:40
Posted: 2010/09/07
File Size: 539249
refile



CSG-F.85-08.230X.JPG

Taken: 2008/03/28 9:39
Posted: 2010/09/07
File Size: 624713
refile

CSG-F.85-08.230W.JPG

Taken: 2008/03/28 9:38
Posted: 2010/09/07
File Size: 573674
refile



CSG-F.85-08.230V.JPG

Taken: 2008/03/28 9:37
Posted: 2010/09/07
File Size: 550694
refile

CSG-F.85-08.230U.JPG

Taken: 2008/03/28 9:35
Posted: 2010/09/07
File Size: 555643
refile



CSG-F.85-08.230T.JPG

Taken: 2008/03/28 9:29
Posted: 2010/09/07
File Size: 555189
refile

CSG-F.85-08.230S.JPG

Taken: 2008/03/28 9:28
Posted: 2010/09/07
File Size: 591315
refile



CSG-F.85-08.230R.JPG

Taken: 2008/03/28 9:26
Posted: 2010/09/07
File Size: 534367
refile

CSG-F.85-08.230Q.JPG

Taken: 2008/03/28 9:02
Posted: 2010/09/07
File Size: 577111
refile



CSG-F.85-08.230P.JPG

Taken: 2008/03/28 9:00
Posted: 2010/09/07
File Size: 546071
refile

CSG-F.85-08.2300.JPG

Taken: 2008/03/28 9:00
Posted: 2010/09/07
File Size: 559272
refile



CSG-F.85-08.230N.JPG

Taken: 2008/03/28 8:59
Posted: 2010/09/07
File Size: 597344
refile

CSG-F.85-08.230M.JPG

Taken: 2008/03/28 8:59
Posted: 2010/09/07
File Size: 512402
refile



CSG-F.85-08.230L.JPG

Taken: 2008/03/28 8:57
Posted: 2010/09/07
File Size: 540522
refile

CSG-F.85-08.23 SPALLING WITH EXPOSED REBAR IN SOUTH END OF P.JPG

Taken: 2006/07/21 11:05
Posted: 2008/09/04
File Size: 49736
e:\web\offsystem\CSG-F.85-08.23\



CSG-F.85-08.23 SPALLING WITH EXPOSED REBAR IN SOUTH END (2).JPG

Taken: 2006/07/21 11:05

Posted: 2008/09/04

File Size: 55418

e:\web\offsystem\CSG-F.85-08.23\

CSG-F.85-08.23 SPALLING WITH EXPOSED REBAR IN SOUTH END (1).JPG

Taken: 2006/07/21 11:05

Posted: 2008/09/04

File Size: 74880

e:\web\offsystem\CSG-F.85-08.23\



**CSG-F.85-08.23 JOINT
CONDITION ABOVE PIER 4.JPG**

Taken: 2006/07/21 11:05
Posted: 2008/09/04
File Size: 75279
e:\web\offsystem\CSG-F.85-08.23\

**CSG-F.85-08.23 JOINT
CONDITION ABOVE PIER 3.JPG**

Taken: 2006/07/21 11:05
Posted: 2008/09/04
File Size: 76679
e:\web\offsystem\CSG-F.85-08.23\



CSG-F.85-08.23 CRACKS WITH EFFLORESCENCE IN SOFFIT.JPG

Taken: 2006/07/21 11:05

Posted: 2008/09/04

File Size: 28686

e:\web\offsystem\CSG-F.85-08.23\

Picture212.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 48819



Picture211.jpg

Taken: 2004/07/01 2:10
Posted: 2007/11/21
File Size: 33497

Picture210.jpg

Taken: 2004/07/01 2:10
Posted: 2007/11/21
File Size: 26285



Picture209.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 78957

Picture208.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 38603



Picture207.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 36112

Picture206.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 38823



Picture205.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 61857

Picture204.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 67118



Picture203.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 55538

Picture202.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 57384



Picture201.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 70509

Picture200.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 74271



Picture199.jpg

Taken: 2004/07/01 2:10

Posted: 2007/11/21

File Size: 42165