

Resolution #TC-17-5-4

Fiscal Year 2018 over \$50,000 project list approval

Approved by the Transportation Commission on May 18, 2017

WHEREAS, under Senate Bill 98-148, public projects supervised by the Colorado Department of Transportation (CDOT) are exempt from the requirements of the “Construction Bidding for Public Projects Act;” and

WHEREAS, Section 24-92-109, Colorado Revised Statutes, as amended, requires CDOT to prepare cost estimates for projects to be undertaken by CDOT maintenance crews that exceed \$50 thousand, but are less than or equal to \$150 thousand for submission to the Transportation Commission for review and approval; and

WHEREAS, CDOT staff have prepared a cost estimate for these projects to be done in Fiscal Year 2018 as detailed in the memorandum entitled; FY 18 Maintenance \$50,000 to \$150,000 project list.

WHEREAS, the funding for this project is contained in the Fiscal Year 2018 Budget.

NOW THEREFORE BE IT RESOLVED, the Transportation Commission has reviewed the cost estimate, as contained in the official agenda, and approves CDOT Maintenance Forces undertaking the project therein.

FY 2018 Region 4 Section 1 Surface Treatment				
Hwy	Start	End	Type	Estimated Cost
70A	394.00	420.00	Crack Seal	\$ 91,269
70A	383.50	388.50	Machine Patch Overlay	\$ 149,750
119 A	23.50	24.50	Machine Patch Overlay	\$ 144,000
007 A	6.00	8.00	Machine Patch Overlay	\$ 148,485
072A	33.00	38.00	Chip Seal	\$ 148,621
76	78.49	82.16	Machine Patch Overlay	\$ 149,000
71	170.60	171.70	Machine Patch Overlay	\$ 121,540
34	249.71	Bridge	Mill and Fill Overlay	\$ 108,549
34A	112.44	112.92	Machine Patch Overlay	\$ 80,189
34A	142.26	148.80	Chip Seal	\$ 149,000
014B	64.90	66.20	Machine Patch Overlay	\$ 145,483

014B	109.00	115.00	Chip Seal	\$ 144,101
138	36.00	43.00	Chip Seal	\$ 148,549
6	380.57	385.57	Chip Seal	\$ 148,450
				\$ 1,876,986

FY 2018 Region 3 Section 2 Surface Treatment

Hwy	Start	End	Type	Estimated Cost
009D	124.00	124.60	Machine Patch Overlay	\$ 60,403
006F	225.40	226.10	Machine Patch Overlay	\$ 73,407
050A	64.00	66.00	Machine Patch Overlay	\$ 100,000
347A	0.00	1.00	Machine Patch Overlay	\$ 110,000
149A	114.00	117.42	Chip Seal	\$ 100,000
114A	12.00	19.00	Chip Seal	\$ 135,000
82A	54.00	57.00	Machine Patch Overlay	\$ 134,500
70A	119.00	125.00	Mill and Fill Overlay	\$ 125,000
70A	98.00	109.00	Mill and Fill Overlay	\$ 125,000
Hwy 6	85.00	89.00	Chip Seal	\$ 145,000
070A	191.00	196.50	Machine Patch Overlay	\$ 65,436
070A	201.00	213.50	Machine Patch Overlay	\$ 83,893
330A	3.00	4.00	Machine Patch Overlay	\$ 100,000
50A	40.00	46.00	Mill and Fill Overlay	\$ 130,000
65A	0.00	0.30	Mill and Fill Overlay	\$ 90,000
131B	0.30	3.00	Chip Seal	\$ 126,000
70A	180.55	180.80	Mill and Fill Overlay	\$ 66,625
70A	181.63	181.84	Mill and Fill Overlay	\$ 59,558
82	72.00	78.00	Chip Seal	\$ 145,127
82	83.12	85.12	Chip Seal	\$ 90,000
				\$ 2,064,949

FY 2018 Region 5, Section 3 Surface Treatment

Hwy	Start	End	Type	Estimated Cost
184A	0	0.3	Machine Patch Overlay	\$ 64,887
141A	5.1	5.6	Machine Patch Overlay	\$ 75,315

141A	14.9	15.4	Machine Patch Overlay	\$ 75,315
141A	18.4	18.9	Machine Patch Overlay	\$ 50,210
145A	11	11.9	Machine Patch Overlay	\$ 135,567
160A	17	18.29	Chip Seal	\$ 56,982
145A	46.24	47.54	Chip Seal	\$ 68,909
550A	10	12.6	Chip Seal	\$ 130,094
550B	32.8	36	Chip Seal	\$ 143,083
160a	99	100	Machine Patch Overlay	\$ 123,594
550b	36.7	37.6	Machine Patch Overlay	\$ 143,173
550a	4.3	4.75	Machine Patch Overlay	\$ 143,173
160A	101	101.6	Machine Patch Overlay	\$ 129,774
145	107.8	108.6	Machine Patch Overlay	\$ 136,313
145	112.8	113.6	Machine Patch Overlay	\$ 136,313
550	106.5	107.2	Machine Patch Overlay	\$ 147,334
550	113.25	114.05	Machine Patch Overlay	\$ 148,242
141	29.7	30.8	Machine Patch Overlay	\$ 147,463
141	45.8	46.9	Machine Patch Overlay	\$ 147,463
141	57.3	58.3	Machine Patch Overlay	\$ 142,391
141	29	30	Machine Patch Overlay	\$ 143,833
550	56	61	Chip Seal	\$ 148,000
550	72	77	Chip Seal	\$ 148,000
550	80	85	Chip Seal	\$ 148,000
145	84.25	89.25	Chip Seal	\$ 148,000
145	94.25	99.25	Chip Seal	\$ 148,000
160A	2	2.3	Machine Patch Overlay	\$ 69,522
160A	3.4	3.8	Machine Patch Overlay	\$ 92,696
084A	3.60	7.60	Chip Seal	\$ 147,451

				\$ 3,539,097
FY 2018 Region 2, Section 4 Surface Treatment				
Hwy	Start	End	Type	Estimated Cost
10A	39.00	43.02	Chip Seal	\$ 141,032
50A	289.77	294.77	Chip Seal	\$ 148,776
09A	42.00	49.90	Chip Seal	\$ 147,843
24G	326.00	329.00	Chip Seal	\$ 148,194
78A	12.80	17.00	Chip Seal	\$ 149,373
96A	39.10	44.10	Chip Seal	\$ 147,740
165A	9.00	13.50	Chip Seal	\$ 149,623
I-25 F	101.00	102.00	Blade patch W/Chips	\$ 52,674
96A	8.35	9.70	Machine Patch Overlay	\$ 145,448
69A	51.50	53.00	Machine Patch Overlay	\$ 149,803
094A	4.10	7.00	Chip Seal	\$ 142,615
083A	24.00	28.13	Chip Seal	\$ 148,363
025A	153.00	153.00	Machine Patch Overlay	\$ 127,196
025A	152.00	152.00	Machine Patch Overlay	\$ 118,157
115A	38.90	40.00	Chip Seal	\$ 145,173
024G	322.27	323.38	Machine Patch Overlay	\$ 89,977
101A	8.00	9.00	Machine Patch Overlay	\$ 147,925
10A	58.00	59.00	Machine Patch Overlay	\$ 149,841
266A	4.00	5.00	Machine Patch Overlay	\$ 146,375
50B	380.90	383.90	Chip Seal	\$ 147,100
71C	19.30	23.30	Chip Seal	\$ 147,100
50B	412.30	416.00	Chip Seal	\$ 147,100
160C	345.77	346.15	Machine Patch Overlay	\$ 148,468
10A	19.98	21.27	Machine Patch Overlay	\$ 147,823
12A	42.85	44.15	Machine Patch Overlay	\$ 148,969
160C	353.25	357.50	Chip Seal	\$ 149,002
12A	45.75	50.00	Chip Seal	\$ 149,002
25F	41.48	46.10	Chip Seal	\$ 148,476
69A	11.80	16.00	Chip Seal	\$ 147,249

196A	0.00	3.28	Chip Seal	\$ 149,897
96C	130.50	133.53	Chip Seal	\$ 149,237
116A	3.00	6.20	Chip Seal	\$ 148,173
96C	163.07	166.11	Chip Seal	\$ 149,657
160c	425.60	426.80	Machine Patch Overlay	\$ 149,756
116a	11.50	12.70	Machine Patch Overlay	\$ 149,978
160c	465.00	466.20	Machine Patch Overlay	\$ 149,890
009A	34.00	38.00	Chip Seal	\$ 141,500
024A	287.00	288.00	Machine Patch Overlay	\$ 146,700
285D	161.00	166.00	Chip Seal	\$ 148,500
				\$ 5,559,706

FY 2018 Region 1, Section 5 Surface Treatment

Hwy	Start	End	Type	Estimated Cost
70	270.70	272.20	Mill and Fill Overlay	\$ 132,900
121	16.80	17.30	Mill and Fill Overlay	\$ 129,000
287	290.20	290.80	Mill and Fill Overlay	\$ 132,600
C470 & EB70	470/0	70/261	Mill and Fill Overlay	\$ 87,900
72	7.50	8.50	Machine Patch Overlay	\$ 134,400
70	291.10	291.00	Mill and Fill Overlay	\$ 105,100
79	1.60	1.80	Mill and Fill Overlay	\$ 58,000
76	7.10	7.60	Mill and Fill Overlay	\$ 150,000
7	67.00	67.95	Machine Patch Overlay	\$ 120,000
70	310.00	311.00	Machine Patch Overlay	\$ 90,000
8	7.68	8.50	Mill and Fill Overlay	\$ 90,900
8	5.91	6.30	Mill and Fill Overlay	\$ 127,500
121B	1.00	2.20	Mill and Fill Overlay	\$ 98,900
40	286.84	287.20	Mill and Fill Overlay	\$ 74,900
8	2.80	3.30	Mill and Fill Overlay	\$ 126,800
83	58.50	57.10	Mill and Fill Overlay	\$ 110,000
85	185.30	184.70	Mill and Fill Overlay	\$ 90,000
25F (West)	173.90	174.70	Mill and Fill Overlay	\$ 120,000
				\$ 1,978,900

FY 2018 Region 3, Section 6 Surface Treatment

Hwy	Start	End	Type	Estimated Cost
040A	15.40	16.85	Machine Patch Overlay	\$ 143,541
040A	27.50	29.00	Machine Patch Overlay	\$ 148,491
064A	27.00	28.35	Machine Patch Overlay	\$ 142,703
13B	111.00	112.70	Machine Patch Overlay	\$ 141,247
040A	121.80	122.30	Machine Patch Overlay	\$ 144,716
040A	100.90	102.00	Mill and Fill Overlay	\$ 140,554
040A	107.00	107.40	Mill and Fill Overlay	\$ 76,666
040A	157.00	157.40	Mill and Fill Overlay	\$ 149,898
040A	159.27	160.00	Machine Patch Overlay	\$ 132,225
125A	31.15	31.80	Machine Patch Overlay	\$ 87,580
				\$ 1,307,621

FY 2018 Region 5, Section 7 Surface Treatment

Hwy	Start	End	Type	Estimated Cost
114A	38.50	43.50	Chip Seal	\$ 115,000
17B	109.30	114.30	Chip Seal	\$ 127,055
285 B	102.00	107.00	Chip Seal	\$ 141,000
24A	194.50	199.50	Chip Seal	\$ 141,000
17A	28.50	33.50	Chip Seal	\$ 140,000
159A	30.00	33.00	Chip Seal	\$ 149,000
15B	23.00	28.00	Chip Seal	\$ 140,000
114A	28.40	29.50	Machine Patch Overlay	\$ 145,000
114A	32.20	33.30	Machine Patch Overlay	\$ 149,000
17A	21.00	22.00	Machine Patch Overlay	\$ 100,000
50 A	182.50	183.50	Machine Patch Overlay	\$ 149,000
50 A	184.50	185.50	Machine Patch Overlay	\$ 149,000
17A	1.70	2.70	Machine Patch Overlay	\$ 149,000
370A	11.80	14.00	Machine Patch Overlay	\$ 149,000

160A	156.70	157.40	Machine Patch Overlay	\$ 148,000
				\$ 2,091,055
FY 2018 Region 1, Section 9 Surface Treatment				
Hwy	Start	End	Type	Estimated Cost
70A	233.50	234.20	Mill and Fill Overlay	\$ 102,995
46A	2.00	2.80	Machine Patch Overlay	\$ 80,538
72A	28.40	29.00	Machine Patch Overlay	\$ 55,757
70A	241.30	241.90	Mill and Fill Overlay	\$ 65,050
40A	244.30	244.70	Machine Patch Overlay	\$ 55,757
70A	250.97	251.50	Mill and Fill Overlay	\$ 57,460
70FR	253.52	254.04	Mill and Fill Overlay	\$ 84,564
74A	1.95	2.40	Mill and Fill Overlay	\$ 90,605
				\$ 592,726

Sufficient funds exist within the appropriate MPA's to pursue this project. The project is in accordance with the directive and all other requirements.

Herman F. Stockinger III
Herman Stockinger, Secretary
Transportation Commission of Colorado

5-18-17
Date

