

# MEMORANDUM

DEPARTMENT OF TRANSPORTATION  
Staff Bridge Branch  
4201 E. Arkansas Avenue, Room 107  
Denver, Colorado 80222  
(303) 757-9309 FAX (303) 757-9197



Date: May 1, 2009

To: All Bridge Design Manual Users

*Signature on File*

From: Mark A. Leonard, Bridge Branch Manager

Subject: CDOT Bridge Design Manual Revisions

The following subsections of the CDOT Bridge Design Manual has been updated or added:

Revision Log  
Table of Contents  
Subsection 3.3 – Collision Load (CT)

This addition is available through the CDOT bridge web page.

<http://www.dot.state.co.us/Bridge/DesignManual/BridgeDesignManual.htm>

Please review and become familiar with this addition. If you have any questions or recommendations for improvement please contact:

[Mahmood.Hasan@dot.state.co.us](mailto:Mahmood.Hasan@dot.state.co.us) 303-757-9064

MAL/MH/mh

Distribution via e-mail:

Hutton	Program Engineers
Gabel	Resident Engineers
Greer, FHWA	Staff Bridge Employees
Branch Managers	Structural Consultants