



COLORADO
Department of Transportation
Office of the Chief Engineer

Staff Bridge Branch
2829 W. Howard Place, 3rd Floor
Denver, CO 80204

MEMORANDUM

DATE: MONDAY, MARCH 15, 2021
TO: ALL BRIDGE DETAIL MANUAL USERS
FROM: STAFF BRIDGE BRANCH MANAGER
SUBJECT: CDOT BRIDGE DETAIL MANUAL REVISIONS

The following sections of the CDOT Bridge Detail Manual have been updated and created:

- Table of Contents
- Revision Log
- Chapter 11 - Abutment Details
- Chapter 13.3 - Prestressed Concrete Superstructure Details (New)

Please add these sections to your copy of the Bridge Detail Manual. These revisions are available electronically through the CDOT bridge web page.

<http://www.codot.gov/library/bridge/bridge-manuals/bridge-detail-manual>

Please review and become familiar with these revisions. If you have any questions or recommendations for improvement, please contact:

hoang.bui@state.co.us

(303) 512-4075

HB/dc

Distribution via e-mail:

Keith Stefanik

Staff Bridge Employees

Structural Consultants

