

MEMORANDUM

DEPARTMENT OF TRANSPORTATION

Staff Bridge Branch
4201 E. Arkansas Avenue, Room 107
Denver, Colorado 80222
(303) 757-9309 FAX (303) 757-9197



Date: April 1, 2011

To: All Bridge Rating Manual Users

Signature on File

From: Mark A. Leonard

Subject: CDOT Bridge Rating Manual Additions & Revisions

The following Sections of the CDOT Bridge Rating Manual have been added to address LRFR (Load and Resistance Factor Rating):

Section 14 - Concrete Box Culverts
Section 15 - Load and Resistance Factor Rating (LRFR)

The following Sections of the CDOT Bridge Rating Manual have been revised to address LRFR (Load and Resistance Factor Rating) and other rating related issues:

Table of Contents
Introduction
Revision Log
Section 1 - General Requirements
Section 8 - Reinforced Concrete Structures

Please add these sections to your copy of the Bridge Rating Manual. These revisions are available electronically through the CDOT bridge web page.

<http://www.dot.state.co.us/DesignSupport/>

Structural personnel should review and become familiar with these additions/revisions. If you have any questions or recommendations for improvement please contact:

M. Mac Hasan, Project Support Unit (303) 757-9064
mahmood.hasan@dot.state.co.us

J.W. Gregory, Bridge Rating and Overloads Unit (303) 512-4012
john.gregory@dot.state.co.us

April 1, 2011
Mark A. Leonard
CDOT Bridge Rating Manual Additions & Revisions
Page - 2

Attachments

MAL/MH/mh

Distribution via e-mail:

Scott McDaniel, CDOT - Director of Staff Services
Matt Greer, FHWA
Staff Bridge Employees
Structural Consultants