



Staff Bridge Branch  
2829 W. Howard Place, 3<sup>rd</sup> Floor  
Denver, CO 80204

MEMORANDUM

DATE: Thursday, July 21, 2022  
TO: All Bridge Worksheet Users  
FROM: Michael Collins, Staff Bridge Branch Manager  
SUBJECT: CDOT Bridge Worksheets Updates

The following worksheets have been updated and are now available. Individual changes are identified in the following paragraphs.

These updates, and all of the worksheets, are available through the CDOT bridge web page.  
<http://www.codot.gov/library/bridge/design-standards>

B-INDEX-2: Updated revisions log and revision table cells for this submittal.

B-606-9A: Updated reinforcing quantity, added excavation, backfill to be included in the pay item.

B-606-9B: Updated reinforcing quantity, added excavation, backfill, expansion joint material & joint sealing to be included in the pay item.

B-606-9C: Updated reinforcing quantity, added excavation, backfill to be included in the pay item. Added top bar dimensions.

B-606-9D: Updated reinforcing quantity, added excavation, backfill, expansion joint material & joint sealing to be included in the pay item. Added top bar dimensions.

B-606-10MASHA: Updated reinforcing quantity, added excavation, backfill to be included in the pay item. Revised front bar dimension and stirrups in Section D. Added clear distance and corrected top bar locations in sections.

B-606-10MASHA-S: Updated reinforcing quantity and details in sections, added excavation, backfill, expansion joint material & joint sealing to be included in the pay item. Revised front bar dimension and stirrups in Section C. Added clear distance and corrected top bar locations in sections.

B-606-10MASHB: Updated sheet so it can be used with both A & A-S

B-606-10MASHB-S: Deleted and all information incorporated into B-606-10MASHB.



B-606-10MASHC: Updated reinforcing quantity, added excavation, backfill to be included in the pay item.

B-606-10MASHC-S: Updated reinforcing quantity, added excavation, backfill, expansion joint material & joint sealing to be included in the pay item. Revised bar dimension in Section C

B-606-10MASHD: Fixed Minor Typos

Please review and become familiar with these revisions. If you have any questions or recommendations for improvement to the worksheets, please contact:

[Hoang.bui@state.co.us](mailto:Hoang.bui@state.co.us) (303) 512-4075

MPC/ajp

Distribution via e-mail:

Keith Stefanik Staff Bridge Employees

Structural Consultants

