

Staff Bridge Branch 2829 W. Howard Place, 3<sup>rd</sup> Floor Denver, CO 80204

## MEMORANDUM

DATE:	Monday, June 24, 2019
TO:	All Bridge Worksheet Users
FROM:	Michael Collins, Staff Bridge Branch Manager
SUBJECT:	CDOT Bridge Worksheets Additions and Updates

The following worksheets have been updated and new worksheets are now available. Individual changes are identified in the following paragraphs.

These updates, and all of the worksheets, are available through the CDOT bridge web page.

http://www.codot.gov/library/bridge/design-standards

B-INDEX-1: Updated revisions log and revision table cells for this submittal.

B-INDEX-2: Updated revisions log and revision table cells for this submittal.

B-606-8RMASHA: New Worksheet for Glenwood Canyon Bridge Rail Tube replacements.

B-606-8RMASHB: New Worksheet for Glenwood Canyon Bridge Rail Tube replacements.

B-618-BT: Removed Worksheet.

B-618-DF: Removed Worksheet.

Please review and become familiar with these revisions. If you have any questions or recommendations for improvement to the worksheets, please contact:

<u>Hoang.bui@state.co.us</u> (303) 512-4075

Distribution via e-mail:

Jared Esquibel

Staff Bridge Employees

Structural Consultants

