



COLORADO

Department of Transportation

-US 50 Monarch Pass Runaway Truck Ramp Closed- *Commercial truckers traveling eastbound are urged to use extreme caution*

TRUCK RAMP CLOSURE

- September - October, 2022
- US Highway 50, mile point 204, four miles east of the Monarch Pass summit
- Monarch Pass is located on US 50 between Sargents and Poncha Springs (47 miles east of Gunnison)
- Only available eastbound truck ramp will be closed


PROJECT OVERVIEW

CDOT will repair sinkholes and replace a failed culvert. The new concrete culvert design will lower the risk of erosion as well as prolong the life of the emergency truck ramp. Guardrails and overhead signage will be upgraded to comply with current safety standards.



TRAVEL IMPACTS

- The **speed limit** will be reduced to **25 mph** through the work zone
- **Delays** can be expected to accommodate periodic movement of equipment or materials
- Intermittent brake and safety checks will be performed near the pass summit (MP 199)



CONTACT INFORMATION

Phone: 970-385-1423

Email: dot_r5_customerservice@state.co.us

Project Webpage: www.codot.gov/projects/us50-monarch-emergency-truck-ramp

