




SH 9 and Fairview Boulevard Intersection

Summary of Current Status

- A study was completed and the intersection currently meets Warrant 2, Four Hour Volumes.
- Currently, there is no funding available to construct the signal.
- Stan Miller Drive will be constructed this Summer before a traffic signal can be funded, designed and constructed
- Stan Miller Drive will provide a connection between Fairview Boulevard and Tiger Road and change access to area businesses. It may also affect the Warrant results.
- A follow up study is recommended after construction of Stan Miller Drive and SH 9 construction is complete to determine whether traffic signal warrants will be met in the future.
- If the intersection continues to meet MUTCD Warrants, CDOT, the County and Town will continue to pursue opportunities to construct the signal with other projects.



Northbound SH 9



Southbound SH 9



State Highway 9 at Fairview Boulevard Looking South



Eastbound Fairview Blvd



Westbound Fairview Blvd

