

# NOTICE

## I-25 & Fillmore Interchange

### PERMANENT LEFT TURN LANE CLOSURE TO SINTON ROAD

On Sunday, November 8, the Colorado Department of Transportation (CDOT) permanently removed left turn access from Fillmore Street to Sinton Road. Traffic will only be allowed to make right-turns in and out of Sinton Road access points along Fillmore Street.

The Diverging Diamond Interchange (DDI) is intended to alleviate traffic congestion on Fillmore Street, while increasing safety through the interchange.

### OTHER DDI BENEFITS

- Improved traffic flow through the completed interchange - less delay for motorists accessing local businesses
- Elongated I-25 southbound deceleration off-ramp and I-25 northbound acceleration on-ramp lengths
- Dedicated left-turn movements onto I-25 on-ramp system (free flowing)
- Architectural Enhancements to interchange bridge structures, improved highway lighting system
- Increased safety to motorists travelling through the interchange
- Improved pedestrian access across the interchange (14 foot sidewalk system on eastbound bridge structure)
- Dedicated Bike Lanes both east and westbound Fillmore Street through the interchange

The intersection work is part of a CDOT interchange reconstruction project. Completion is scheduled for summer 2016.

### CONTACT THE PROJECT TEAM

If you have questions about the I-25 & Fillmore Street Exchange project, contact the Public Information Team at.

November 2015

Email: [i25fillmore@PublicInfoTeam.com](mailto:i25fillmore@PublicInfoTeam.com)

Phone: 719-367-4884



**COLORADO**  
Department of  
Transportation