



## **Bustang ADA Survey Checklist**

Location: Vail Transportation Center

Date: September 29, 2016

Survey Conducted By: Patrick Going, ADA Consultant

Parking & Drop-Off Area No Parking Specifically for Bustang Provided

COMMENTS: There are several public parking lots available.

Exterior Path-of-Travel to Bustang Loading Area	YES	NO
Is the walkway to the bus loading area paved, relatively flat, and free of abrupt edges or breaks in the surface?	X	
Are all curbs along walkway ramped?	X	
Are stairs or steps along the walkway either ramped or have alternative means of access (e.g. elevator)?	X	
Is the walkway/hallway 36" minimum width and free of protrusions or overhanging obstacles?	X	

## COMMENTS: Like all the Bustang stops, larger signs are recommended.

Bustang Bus Waiting Shelter	YES	NO	
Is the shelter on an accessible route with adequate clearance to enter and accessible benches (if provided).	X		

Restrooms	YES	NO	
If restrooms provided, is there an accessible restroom (signage, doors pressure <5 lbs, toilet height, grab bars, accessible sink)? No restrooms specifically for Bustang. Vail Information/Visitor Building provides restrooms.	-		

## **COMMENTS:** Restrooms available in Information building.

Local Connecting Transportation	YES	NO
Is public transportation available? Vail Transit, ECO Transit, Greyhound	X	
Local bus stop less than 1/4 mile to Bustang loading area?	X	
Is route from local bus stop to Bustang stop accessible? (Will be once construction complete)	X	

Other	YES	NO
Ticket counter accessible (if provided)? No higher than 36". N/A - pay on bus	-	
Rider information (schedules, fares, etc.) properly displayed and available in large print or alternate format? No schedule displayed at outside Bustang stop.	-	





