

Arriba Rest Area I-70 MM 383.3
Elevation \approx 5239'

CDOT Region #4



Summary Observations

An on-site ADA survey was conducted September 1, 2016, by Patrick Going, ADA Consultant. All observations are based on the *2010 ADA Standards for Accessible Design*. These Standards may be found at www.access-board.gov.

This rest area is well maintained and convenient to either westbound or eastbound traffic on I-70. It is accessible for people with disabilities with the exception there are no full size accessible toilet stalls.

Parking

There are 26 parking spaces with two (2) designated accessible parking spaces on the south side. There is a narrow access aisle between these two spots. There is a requirement that 1:6, but no less than one, of the accessible spaces be a 'van' space (§208.2.4).

On the north side there is a large RV configured accessible parking area. It resembles a driveway that leads to the building. There are no defining parking space lines or access aisles marked. The accessible sign is at the bottom of this paved area. The running slope exceeds 1:20 and cross slope exceeds 2%.

There is a separate parking area for RV's and trucks.

Path-of-Travel

The route from the two accessible parking spaces on the south side and the one RV space on the north side to the building is acceptable.

Rest Rooms

The rest rooms are basically OK, but do need a few minor corrections. Add a restroom sign on the wall on the latch side of door for the men's and women's restrooms. There is an ambulatory toilet stall in each restroom.

Vending Machines and Visitor Information

All outside and inside information signs are acceptable. There are no vending machines.

Dog Relief Areas

There are several 'dog relief' areas. Most are accessible for people with assistive mobility devices.



ADA Graded Summary*

*Based on 2010 ADA Standards for Accessible Design



Excellent



Moderate



Poor

Parking	Path-of-Travel to Bldg/Services	Restrooms	Vending/Picnic Tables
			
26 spaces/2 accessible on south side. 1 unorthodox accessible parking area on north side. Add 'van' on 1 vertical sign at one of south spaces.	Paved surface, curb cuts, OK slope	Women's & Men's - add signs with raised letters & Braille on wall, latch side. Reduce door opening pressure \leq 5 lbs.	No vending machines. Picnic tables - good Pet area - OK

Recommendations	
Description	Priority
Reduce restroom door pressures to \leq 5 lbs of force	Immediate
Add restrooms signs, raised letters and Braille, on wall, latch side of door at men's and women's restrooms.	Immediate
At the two current accessible parking spaces on south side refresh faded paint and make access aisle 8'. Add 'van' to one post.	Immediate







