

Gobblers Knob Rest Area - US 287 MM 55.20
Elevation \approx 5600'

CDOT Region #2



Summary Observations

An on-site ADA survey was conducted September 1, 2016, by Patrick Going, ADA Consultant. All observations are based on the 2010 ADA Standards for Accessible Design. These Standards may be found at www.access-board.gov.

This rest area is marginally accessible to people with disabilities. It does not have any running water.

Parking

The one accessible parking spaces for automobiles meets the minimum ADA scoping requirements (1:25) as there are less than 25 'regular' spaces (**16 total spaces**). There is a requirement that 1:6, but no less than one, of the accessible spaces be a 'van' space. There is space for a 8' wide access aisle at the accessible parking space that would accommodate the 'van' designation.

There are four separate parking spaces for RV's and trucks. Although there is not a designated accessible parking space for trucks or RVs, an accessible path to the building is provided.

Path-of-Travel

The route from the current accessible car parking spaces to the building is acceptable.

Rest Rooms

The men's and women's restrooms have adequate maneuvering space. These are 'pit' toilets as there is no running water. Braille is needed on the Men's restroom sign.

Vending Machines and Visitor Information

There are no vending machines. The visitor information sign is not on an accessible path.

Dog Relief Areas

There are numerous designated 'dog relief' areas. Most are accessible for people with assistive mobility devices.



ADA Graded Summary*
***Based on 2010 Standards for Accessible Design**






Excellent



Moderate



Poor

Parking 	Path-of-Travel to Building/Services 	Restrooms 	Vending/Picnic Not available
16 spaces/1 accessible. Add 'van' on the one vertical sign at the one accessible parking space	Paved surface, curb cuts, running slope is ADA compliant at less than 20% grade	Women's - pit toilet. Heavy exterior door Men's - add Braille to sign. Heavy exterior door	Pet area available No vending or picnic tables

Recommendations	
Description	Priority
If it is practical due to wind and environment, reduce door pressures at the two exterior restroom doors for easier opening	Immediate
Add a 'van' sign on vertical sign at the one accessible parking space	Immediate
Stripe 8' wide access aisle to right of the one accessible parking space	Immediate
Add Braille at Men's restroom sign	Immediate

