
Julesburg - I-76 MM 180.5 Elevation ≈ 3475'

CDOT Region #4





Summary Observations

An on-site ADA survey was conducted September 17, 2016, by Patrick Going, ADA Consultant. All observations are based on the *2010 ADA Standards for Accessible Design*. These Standards may be found at www.access-board.gov.

This rest area is well maintained and generally very accessible to people with disabilities. Ample parking for cars, RVs, and trucks.

Parking

There are 2 parking area, each with approximately 26 parking spaces and with three (3) designated accessible parking spaces. There are two instances where the spaces adjoin a wide 8' access aisle - which can accommodate the 'van' requirement.

There are additional parking areas for RV's and trucks.

Path-of-Travel

The route from the current accessible parking spaces to the building is ADA compliant.

Rest Rooms

The men's, women's, and family restrooms are ADA compliant.

Vending Machines, Picnic Tables, and Visitor Information

No vending machines. The picnic tables and visitor information boards are accessible.

Dog Relief Areas

There are numerous designated 'dog relief' areas.



ADA Graded Summary* *Based on 2010 ADA Standards for Accessible Design



Excellent



Moderate



Poor

Parking Excellent	Path-of-Travel to Building/Services	Restrooms	Vending/Picnic Tables
Auto - 2 areas - main entrance has 28 spaces/3 accessible & other area by trucks 25 spaces/3 accessible space. Truck and RV parking is good.	Paved surface, curb cuts, OK slope	Women's, Men's, & Family - ADA accessible.	No vending machines Pet area, picnic tables accessible

Recommendations			
Description	Priority		
Add 'van' sign to post at space next to a large access aisle.	Immediate		
At family restroom add sign on latch side of door. (Window?)	Immediate		



