

**Shaw Creek - U.S. 160 MM 191.39**  
**Elevation  $\approx$  8000'**

**CDOT Region #5**



## Summary Observations

An on-site ADA survey was conducted October 5, 2016, by Patrick Going, ADA Consultant. All observations are based on the *2010 ADA Standards for Accessible Design*. These Standards may be found at [www.access-board.gov](http://www.access-board.gov).

This is a modern rest area with easy access from US 160 - just east of Wolf Creek Pass. It is supervised and maintained seven days a week. This rest area is relatively flat and very accessible for people with disabilities. The accessible parking just needs two vertical signs. Each rest room lacks a full size accessible toilet stall.

## Parking

There are 25 automobile parking spaces with three designated accessible parking spaces - two on the east side and one on the west side. Two additional vertical signs are needed and a 'van' sign added to the existing vertical post with ISA.

There is a separate paved parking area with five large parking spaces for RV's and trucks. A simple curb cut is needed to create an accessible route to the rest rooms from this RV/Truck area.

## Path-of-Travel

The route from the accessible car parking spaces to the building is ADA compliant.

## Rest Rooms

The men's and women's rest rooms are basically acceptable with the exception that they only have an ambulatory toilet stall, not the full size accessible stall. This would be problematic for anyone who uses a wheelchair and can not manage to use the side grab bars to access the toilet. Add restroom signs on the wall on the latch side of door for the men's and women's restrooms.

The pipes under the sinks need to be wrapped.

## Vending Machines and Visitor Information

There is adequate circulation space to reach the vending machines and visitor information.

**Dog Relief Areas** - There are two designated 'dog relief' areas. They are accessible for people with disabilities who use assistive mobility devices.



**ADA Graded Summary\***  
**\*Based on 2010 ADA Standards for Accessible Design**



Parking	Path-of-Travel to Building/Services	Restrooms	Vending/Picnic Tables
			
25 spaces/3 accessible. Only one vertical sign with ISA.	Paved surface, curb cuts, OK slope	<p><b>Women's</b> wrap sink pipes. No full size accessible toilet stall</p> <p><b>Men's</b> wrap sink pipes. No full size accessible toilet stall</p>	Vending, picnic tables, & pet areas accessible

Recommendations	
Description	Priority
Add two vertical parking sign posts with ISA	Immediate
Add 'van' to one of the vertical accessible parking signs	Immediate
Paint diagonal lines for an access aisle on west side	Immediate
Install signs for the restrooms on wall on latch side of door	Immediate
Reduce opening door pressure on restroom doors	Immediate
Wrap drain pipes under restroom sinks	Soon
Construct a full size accessible toilet stall in each restroom	Future





