



Bustang ADA Survey Checklist

Location: Frisco Transfer Center

Date: September 29, 2016

Survey Conducted By: Patrick Going, ADA Consultant

<i>Parking & Drop-Off Area</i> No Parking Specifically for Bustang Provided	-	-
--	---	---

COMMENTS: This is a large transportation hub with a very large parking lot.

<i>Exterior Path-of-Travel to Bustang Loading Area</i>	YES	NO
<i>Is the walkway to the bus loading area paved, relatively flat, and free of abrupt edges or breaks in the surface?</i>	X	
<i>Are all curbs along walkway ramped?</i>	X	
<i>Are stairs or steps along the walkway either ramped or have alternative means of access (e.g. elevator)?</i>	X	
<i>Is the walkway/hallway 36" minimum width and free of protrusions or overhanging obstacles?</i>	X	

COMMENTS: Like all the Bustang stops, larger signs are recommended. It was difficult to locate this Bustang stop in the evening.

<i>Bustang Bus Waiting Shelter</i>	YES	NO
<i>Is the shelter on an accessible route with adequate clearance to enter and accessible benches (if provided). Adjacent to the Bustang stop is a large, comfortable building with restrooms, vending, etc.</i>	X	

<i>Restrooms</i>	YES	NO
<i>If restrooms provided, is there an accessible restroom (signage, doors pressure <5 lbs, toilet height, grab bars, accessible sink)? No restrooms specifically for Bustang. Building nearby serving Greyhound and other buses did have restrooms.</i>	-	

<i>Local Connecting Transportation</i>	YES	NO
<i>Is public transportation available? Summit Stage, Greyhound</i>	X	
<i>Local bus stop less than 1/4 mile to Bustang loading area?</i>	X	
<i>Is route from local bus stop to Bustang stop accessible? (Will be once construction complete)</i>	X	

<i>Other</i>	YES	NO
<i>Ticket counter accessible (if provided)? No higher than 36". N/A - pay on bus</i>	-	
<i>Rider information (schedules, fares, etc.) properly displayed and available in large print or alternate format? No schedule displayed at outside Bustang stop.</i>	-	

