



Bustang ADA Survey Checklist

Location: South Glenwood BRT Station

Date: September 29, 2016

Survey Conducted By: Patrick Going, ADA Consultant

Parking & Drop-Off Area No Parking Specifically for Bustang Provided

COMMENTS: Only parking available is on an upper parking deck or on-street. Access route from parking deck is via long two-story ramp.

Exterior Path-of-Travel to Bustang Loading Area	YES	NO
Is the walkway to the bus loading area paved, relatively flat, and free of abrupt edges or breaks in the surface?	X	
Are all curbs along walkway ramped?	X	
Are stairs or steps along the walkway either ramped or have alternative means of access (e.g. elevator)?	X	
Is the walkway/hallway 36" minimum width and free of protrusions or overhanging obstacles?	X	

COMMENTS: It is not readily apparent where the Bustang loading area is. See pictures. This sign is only about 14" x 18".

Bustang Bus Waiting Shelter	YES	NO
Is the shelter on an accessible route with adequate clearance to enter and accessible benches (if provided).	X	

Restrooms	YES	NO	
If restrooms provided, is there an accessible restroom (signage, doors pressure <5 lbs, toilet height, grab bars, accessible sink)?	X		

COMMENTS: Public 'Family' restroom available

Local Connecting Transportation	YES	NO
Is public transportation available? RFTA Local, Ride Glenwood Springs	X	
Local bus stop less than 1/4 mile to Bustang loading area?	X	
Is route from local bus stop to Bustang stop accessible? (Will be once construction complete)	X	

Other	YES	NO
Ticket counter accessible (if provided)? No higher than 36". N/A - pay on bus	S _	
Rider information (schedules, fares, etc.) properly displayed and available in large print or alternate format? Did not see rider information displayed at stop.		X











