August 2017 Monthly Operations Report





EXPRESS US EXPRESS 1-25 O Plenary Roads



Table of Contents

1.0	Volumes and Lane Usage	3
2.0	Revenues	5
3.0	Operational Incidents, Issues, and Closures	5
4.0	Mean Time Between Failure (MTBF) and Mean Time to repair (MTTR)	6
5.0	Hybrid Utilization	7

TABLES

Table 1 – Monthly Traffic Summaries	4
Table 2 – Managed Lanes Closures to Date	6
Table 3 – ETCS Issues per CA Schedule 6 Appendix 6-2	6
Table 4 - Status of Noncompliance Categories	7
Table 5 – Mean Time Between Failure & Mean Time To Repair Table 6 – Hybrid Utilization	

FIGURES

Figure 1 – Monthly Traffic Distribution	.4
Figure 2 – Daily Traffic Counts	. 5



INTRODUCTION

Pursuant to Schedule 6, Section 1.8.2(a) of the Concession Agreement, Plenary Roads Denver ("PRD") is required to submit a monthly report covering all essential statistics related to the Managed Lanes. The following data covers the month of August 2017. Operationally, August was a positive month. Several routine maintenance tasks were completed, there were minimal incidents to maintained elements, and traffic volumes were consistent with expectations.

1.0 VOLUMES AND LANE USAGE

Over the last several months as more commuters use the transponders for either ExpressToll[™] (AVI) or HOV travel, License Plate (LPT) transactions have consistently decreased as a percentage of total traffic volume. The total monthly gantry traffic volume for August 2017 in the I-25 Central and US 36 Managed Lanes was 300,837 and 1,363,903, respectively.

The table below provides the monthly summary for each Managed Lanes roadway, along with a detailed breakdown of weekday volumes. For reference, the AM Peak Period is considered to be weekdays from 6:45 am – 8:45 am. The PM Peak Period is considered to be, weekdays, from 4:15pm – 5:45pm. It should be noted, that the I-25 Managed Lane traffic reflects traffic counts from a single gantry and US 36 Managed Lane counts reflect fourteen gantries, seven gantries in each direction. Therefore, US 36 data will indicate far greater traffic counts that are not comparative to those of I-25.


Traffic Summary (US 36)							
AVI LPT HOV Hybrid Total Hybri							
Total Monthly Traffic	756,600	360,988	201,169	45,146	1,363,903	6,481	
Maximum Weekday Traffic	33,825	16,771	7,704	2,063	58,126	334	
Average Weekday Traffic	30,605	13,942	6,658	1,861	53 <i>,</i> 066	257	
Average Hourly AM Peak Traffic	4,457	1,693	692	232	7,074	N/A	
Average Hourly PM Peak Traffic	5,013	2,215	883	238	8,349	N/A	

The following charts depict the distribution of traffic by type (Figure 1) and the daily traffic counts (Figure 2) and for the month.




Traffic Summary (I-25C)								
	AVI	LPT	HOV	Non-Rev & Hybrid	Total	Hybrid		
Total Monthly Traffic	159,257	77,904	49,047	14,629	300,837	2,091		
Maximum Weekday Traffic	7,495	3 <i>,</i> 585	1,989	650	13,628	108		
Average Weekday Traffic	6,485	3,039	1,805	601	11,329	87		
Average Hourly AM Peak Traffic	945	428	253	85	1,626	N/A		
Average Hourly PM Peak Traffic	792	378	225	84	1,395	N/A		

Table 1 – Monthly Traffic Summaries




Monthly Traffic Distribution August 2017 (US 36)

Figure 1 – Monthly Traffic Distribution









2.0 REVENUES

During the month of August 2017, PRD collected \$736,001 and \$677,610 from users of the I-25 Central and US36 Managed Lanes, respectively. For purposes of this report, revenues are recognized at the time of collection, which is typically sometime after they have been incurred for those customers who are billed based on their license plate. For example, if a single-occupant vehicle uses the lanes in October but pays in January, the associated revenue is attributed to January.

3.0 OPERATIONAL INCIDENTS, ISSUES, AND CLOSURES

The project had numerous routine debris removals, lighting incidents, guardrail incidents, sign incidents, and graffiti control during the month. The routine lighting, guardrail, roadway markings and sign incidents are all planned for repair within the allowable response period and several previously identified lighting incidents were repaired. All incidents were responded to and rectified within the allowable timeframes.

Date	Start	Stop	Duration
July 7, 2017	16:45	17:00	0:15
August 2, 2017	07:34	08:22	0:48
August 3, 2017	16:23	17:05	0:42
August 4, 2017	07:23	07:45	0:22
August 9, 2017	08:45	09:43	0:58
August 11, 2017	07:12	07:45	0:33
August 30, 2017	18:00	19:00	1:00



Total		4 hours 38 minutes
Remaining Closure Hours Available (Ref: CA 29.7)		7 hours 22 minutes

Table 2 – Managed Lanes Closures to Date

The table below provides a listing of ETCS items recorded this month, consistent with Appendix 6-2 of Schedule 6.

Element Category	Refer- ence	Element	Performance Item	PRD Notified	Contractual Cure Period	Cure Achieved
None						

 Table 3 – ETCS Issues per CA Schedule 6 Appendix 6-2

The table below provides a status of all Noncompliance categories in accordance with paragraph 1.2 of Schedule 10.

Non- compliance Location	Nature	Cause	Cure Date	Uncured Non- compliance Point	Unexpired Non- compliance Point	365 Day Expiration Date	1095 Day Expiration Date
Promenade West Toll Point	Incorrect toll schedule	Incorrect Toll Schedule was applied during a software update on 3/7/16	3/16/16 (Period II) Customer Accounts Corrected	0	3	3/16/17	3/16/19

Table 4 – Status of Noncompliance Categories

4.0 MEAN TIME BETWEEN FAILURE (MTBF) AND MEAN TIME TO REPAIR (MTTR)

Mean Time Between Failure (MTBF) and Mean Time To Repair (MTTR) data is provided in the table below. Only Maintained Elements that were repaired during the reporting period and had a failure type breakdown are listed in the table. We consider a breakdown to be a failure when the element cannot be used for its intended purpose until repaired.

Maintained Element	Mean Time Between Failure	Mean Time To Repair
	(MTBF) (Hours)	(MTTR) (Hours)



None	N/A	N/A

Table 5 – Mean Time Between Failure & Mean Time To Repair

5.0 HYBRID UTILIZATION

Total Hybrid Trips				
I-25 Central	2,091			
US 36	6,481			

Table 6 – Hybrid Utilization

Fuel-efficient "Hybrid" vehicles are permitted to access the Express Lanes free of charge, regardless of occupant numbers, provided that they have obtained a permit from CDOT, obtained a Hybrid transponder from E-470, and display an E-470 Hybrid decal on the vehicle's windshield.





OPERATIONS AND MAINTENANCE MONTHLY REPORT AUGUST 2017



US 36 and I-25 Express Lanes Project

Prepared for: Plenary Roads Denver, LLC 1700 Lincoln Street, Suite 3000 Denver, CO 80203

Attention: Mr. Simon Stachnik

Prepared By: Broadspectrum 7100-B Pennsylvania Street Thornton, CO 80229 United States of America

> Justin Doles, PE Project Manager





OPERATIONS AND MAINTENANCE – MONTHLY REPORT AUGUST 2017 US 36 and I-25 Express Lanes Project

Revision	Date	Approved
Rev. 0	09/08/2017	Int- De

This report titled Operations and Maintenance Monthly Report, August 2017 has been prepared by Broadspectrum for the exclusive use of Plenary Roads Denver, LLC (PRD). No other party is an intended beneficiary of this report or the information, opinions, and conclusions contained herein. Any use by any party other than PRD of any of the information, opinions, or conclusions is the sole responsibility of said party. The use of this report shall be at the sole risk of the user regardless of any fault or negligence of PRD or Broadspectrum.

The information and analyses contained herein have been completed to a level of detail commensurate with the objectives of the assignment and in light of the information made available to Broadspectrum at the time of preparation. This report and its supporting documentation have been reviewed and/or checked for conformance with industry-accepted norms. To the best of the information and belief of Broadspectrum, the information presented in this report is accurate to within the limitations specified herein.

This report is Broadspectrum pdf file: OM Monthly Report August 2017.pdf. Any reproductions or modifications of this report are uncontrolled and may not be the most recent revision.







The O&M Monthly Report contains all relevant information for the month of August 2017. Broadspectrum continues ongoing and preventive maintenance activities for the I-25 and US36 Managed Lanes Project.

Broadspectrum's Commitment to Safety

Broadspectrum conducted weekly toolbox talk meetings during the month. The purpose of the tool box talks is to cover important safety items that relate to the project such as near misses, "better ways" as to how safety is conducted for the Project, and discussion on safety procedures for maintenance activities. In addition to the toolbox talks, Broadspectrum conducts a weekly progress meeting. This is a forum for feedback from staff on Operations, Incident Response, and Maintenance activities.

Toolbox Talks this month included:

- Incident Reporting
- Impaired Driving
- Top 10 Most Deadly Animals
- Finger Injuries
- BRSA HSE Policy Review

A. Summary of the Planned Maintenance Activities for the Upcoming Month – September 2017

Broadspectrum has identified the upcoming planned maintenance activities as described in Table 1.7.1.3 of The Maintenance Management Plan. These activities include preventative and routine maintenance in order to successfully operate and maintain the Project. A listing of the planned maintenance activities for the month of September 2017 is included below.







Fig. A-1 Planned Maintenance Activities for September 2017

X – Indicates the day the task is planned.

Performance Standard Identification Number (Table	Work Activity- Description	Frequency															Se	p-17														
6.1)			1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
			F	S	S	м	т	w	Т	F	S	S	М	Т	w	Т	F	S	S	м	Т	W	т	F	S	S	М	Т	W	Т	F	S
ML-1	MAINTENANCE PATROL	Daily	Х				Х	х	х	х			Х	Х	х	х	х			х	Х	Х	х	х			Х	х	Х	x	x	
ML-1	FLEXIBLE PAVEMENT OBSERVATION / REPAIR	F-52					x							х							х							х				
ML-1	RIGID PAVEMENT OBSERVATION / REPAIR	F-52					x							х							х							х				
ML-4	DELINEATORS & MARKERS OBSERVE / CLEAN / REPAIR	F-12						х						х						х											x	
ML-2	DRAINAGE (INLET) OBSERVE/ CLEAN / REPAIR	F-12					x																									
ML-2	DRAINAGE (PIPE/CULVERT) OBSERVE / CLEAN / RPR	F-12						х																								
ML-6	SIGN OBSERVATION / REPAIR	F-52					x						х							x							х					
ML-8	STREET LIGHTING OBSERVATION /REPAIR	F-52						х						х							х							х				
ML-8	ELECTRICAL SUPPLY INSPECTION / REPAIR	F-12								x																						
ML-8	ACCESS PANEL OBSERVATION / REPAIR	F-12															х															
ML-10	HERBICIDE & WEED CONTROL MAINTENANCE	F-52						х							х							х							х			
ML-12	GRAFFITI OBSERVATION / REMOVAL	F-52							х							х							х							х		
ML-14	MECHANICAL ROAD SWEEPING	F-12																		х	х	х	х	x								
ML-14	LITTER OBSERVATION / REMOVAL	Daily	х				x	х	x	x			х	х	х	x	х			x	х	х	х	x			х	х	х	x	х	
	REVERSIBLE LANE OPERATIONS	Daily	х				x	x	x	x			х	х	x	x	х			х	х	х	x	x			x	x	х	x	x	

Frequency of Activity:

Daily – Daily Activity

F-4 – Quarterly Activity

F-52 – Weekly Activity

F-2 – Semi-Annual Activity

F-12 – Monthly Activity

F-1 – Annual Activity





B. Summary of Performed and Completed Maintenance Activities

Fig. B-1 Performed and Complete Maintenance Activities for August 2017,

X Indicates the day of the month that the task was completed.

Performance Standard Identification Number (Table	Work Activity- Description	Frequency															A	ug-1	7														
6.1)			1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
			Т	W	Т	F	S	S	М	Т	W	Т	F	S	S	М	Т	w	Т	F	S	S	М	Т	w	т	F	S	S	М	т	w	т
ML-1	MAINTENANCE PATROL	Daily	X	x	X	X			X	x	X	X	X			X	X	X	X	X			X	X	X	X	X			X	x	x	x
ML-1	FLEXIBLE PAVEMENT OBSERVATION / REPAIR	F-52	x						x							x							x							x	x	x	x
ML-1	RIGID PAVEMENT OBSERVATION / REPAIR	F-52	X						X							X							X							X	x		
ML-10	CRACK SEALING	F-1							x	x	x	x	x																				
ML-4	DELINEATORS & MARKERS OBSERVE / CLEAN / REPAIR	F-12		x	x					x							x		x	x				x									
ML-2	DRAINAGE (INLET) OBSERVE/ CLEAN / REPAIR	F-12			x				x	x		x																					
ML-2	DRAINAGE (PIPE/CULVERT) OBSERVE / CLEAN / RPR	F-12															x																
ML-6	SIGN CLEANING	F-1															x																
ML-6	SIGN OBSERVATION / REPAIR	F-52		x	x				x		x							x		x					x							x	
ML-8	STREET LIGHTING OBSERVATION /REPAIR	F-52			x							x							x							x							x
ML-8	ELECTRICAL SUPPLY INSPECTION / REPAIR	F-12								x																							
ML-8	ACCESS PANEL OBSERVATION / REPAIR	F-12															X																
ML-10	HERBICIDE & WEED CONTROL MAINTENANCE	F-52	X	x	x	x			x	x	x	x	x			x	X	x	x				x	x	x						x	x	
ML-12	GRAFFITI OBSERVATION / REMOVAL	F-52	x						x							x			x				x							x			
ML-14	MECHANICAL ROAD SWEEPING	F-12																					X	X	x	x	X						
ML-14	LITTER OBSERVATION / REMOVAL	Daily	X	x	X	x			x	x	x	x	X			X	X	x	X	X			X	X	x	x	X			X	x	x	x
	REVERSIBLE LANE OPERATIONS	Daily	X	x	X	X			x	x	x	X	X			X	X	x	x	X			X	X	x	x	X			X	x	x	x







Fig. B-2 Work Accomplished This Month

Activity	Actual Work
152 Flexible Pavement Surface Rpr (YD2)	60
153 Concrete Pavement Surface Rpr (YD2	12
157 Crack/Joint Seal Concrete Rpr (LF)	80
162 Shouldering Surface Rpr (MI)	0.2
202 Clean Drains (EA)	28
214 Concrete Barrier Rpr (LF)	5
216 Fence Maint (LF)	292
218 Debris in Roadway (HR)	11.4
218 Litter Barrel Trash Cleanup (YD3)	27
220 Sweeping (Mech) (MI)	108
222 Sweeping - Hand (HR)	17.5
253 Vegetation Machine Mowing (ACR)	3
254 Veg Cntrl: Hand/Chem Weeding (HR)	41.5
301 Misc Sign Maint (EA)	3
304 Del Post Maint (EA)	46
314 Reversible Lane Ops (HR)	360
316 Attenuator Maint (EA)	2
329 Courtesy Assistance (HR)	379.5
364 Bridge Joint Maint Cln/Rpr (LF)	774
364 Bridge Joint Rpr (LF)	40
402 Snow Plow Material (HR)	6
540 Graffiti Removal (SF)	20

C. Summary of Planned Maintenance that was Not Completed for the Month

Broadspectum completed all scheduled maintenance activities for the period of August, 2017. Frequencies and/or actual date of the month of some activities may have been adjusted based on actual conditions.

D. Summary of the Maintenance Activities and Results Performed for the Month Beyond Planned Maintenance

A summary of unplanned maintenance activities provided below:

Snow and Ice Control: None

Courtesy Patrol: None

Hazardous Materials Incidents: None





E. Operating Contractor's Incident Response Logs Related to Maintenance Activities

This section provides a summary of Broadspectrum's performance related to the Performance and Measurement Criteria listed in Appendix 6-1.1 of the Operating Contract.

Element				Response to Defects									
Category	Description	Location	BRS Notified	Categ		Category 2							
J. J. J.				Hazard Mitigation	Permanent Remedy	Permanent Repair							
	Lighting	040-l25-LHT-	4/5/2017		N1/A	Reqd: 6 Months							
ML 8.1	(North Bulb Out)	0100, MP 215.0	22:00:00	N/A	N/A	Respd:							
	, ,					Actual: In Progress							
ML 8.1	Lighting	040-I25-LHT-	4/5/2017	N/A	N/A	Reqd: 6 Months Respd:							
IVIL 0.1	(All Bulbs Out)	0050, MP 214.7	22:00:00	N/A	N/A	Actual: In Progress							
						Regd: 6 Months							
ML 8.1	Lighting	040-U36-LHT-	4/5/2017	N/A	N/A	Respd:							
WIE 0.1	(West Bulb Out)	0250, MP 56.8	22:00:00	NVA	N/A	Actual: In Progress							
		_				Regd: 6 Months							
GP 9.2	Fence	US36	5/8/2017	N/A	N/A	Respd: 8/4/2017 10:00							
0. 0.2	(Collision Damage)	MP 49.60 EB	07:00:00	.,,,,		Actual: 2.93 Months							
	•					Regd: 6 Months							
GP 5.2	Attenuator	US36	5/10/2017	N/A	N/A	Respd: 8/2/2017 12:30							
	(Collision Damage)	MP 39.46 WB	12:00:00			Actual: 2.80 Months							
	Pavement Striping	11000	E/47/0047			Reqd: 6 Months							
GP 4.1	(Paint Worn Pavement	US36	5/17/2017	N/A	N/A	Respd:							
	Markings)	MP 39.0-57.1	11:00:00			Actual: In Progress							
	Pavement Striping	I-25	5/17/2017			Reqd: 6 Months							
GP 4.1	(Paint Worn Pavement	MP212.1-217.2	11:00:00	N/A	N/A	Respd:							
	Markings)	IVIF 212.1=217.2	11.00.00			Actual: In Progress							
	Lighting	040-U36-LHT-	6/5/2017			Reqd: 6 Months							
ML 8.1	(West Bulb Out)	0240, MP 56.81	12:00:00	N/A	N/A	Respd:							
	(West Dub Out)	0240, 101 30.01	12.00.00			Actual: In Progress							
	Lighting	040-U36-LHT-	6/5/2017			Reqd: 6 Months							
ML 8.1	(North Bulb Out)	0010, MP 55.40	12:00:00	N/A	N/A	Respd:							
		0010, 111 00.10	12.00.00			Actual: In Progress							
	Lighting	040-I25-LHT-	6/5/2017			Reqd: 6 Months							
ML 8.1	(All Bulbs Out)	0080, MP 214.9	12:00:00	N/A	N/A	Respd:							
						Actual: In Progress							
	Debris	US36	8/2/2017	Reqd: 1 Hours									
GP 1.1	(Cleared Wood from	MP 57.00 EB	14:56:00	Respd: 8/2/2017 15:35	N/A	N/A							
	lanes)			Actual: 0.65 Hours									
GP 1.1	Debris	US36	8/2/2017	Reqd: 1 Hours	N1/A	N1/A							
GP I.I	(Cleared Tire from lanes)	MP 53.00 WB	15:41:00	Respd: 8/2/2017 16:30	N/A	N/A							
	Debris			Actual: 0.81 Hours Regd: 1 Hours									
GP 1.1	(Cleared Ladder from	US36	8/2/2017	Respd: 8/2/2017 16:30	N/A	N/A							
GP 1.1	lanes)	MP 54.70 WB	15:50:00	Actual: 0.66 Hours	IN/A	IN/A							
	Debris			Regd: 1 Hours									
GP 1.1	(Reported Debris,	US36	8/2/2017	Respd: 8/2/2017 11:05	N/A	N/A							
01 1.1	Nothing Found)	MP 43.10 WB	10:38:00	Actual: 0.44 Hours	N/A	11/7							
	Debris			Regd: 1 Hours									
GP 1.1	(Cleared Sign from	US36	8/7/2017	Respd: 8/7/2017 13:05	N/A	N/A							
0	lanes)	MP 41.80 WB	12:39:00	Actual: 0.43 Hours	1 1/73	19/73							
	Debris		0/0/02 /-	Regd: 1 Hours									
GP 1.1	(Reported Debris,	US36	8/8/2017	Respd: 8/8/2017 16:24	N/A	N/A							
	Nothing Found)	MP 40.50 EB	15:35:00	Actual: 0.81 Hours									
	Debris	11000	0/0/0047	Reqd: 1 Hours									
GP 1.1	(Cleared Tire from	US36	8/9/2017	Respd: 8/9/2017 13:53	N/A	N/A							
	lanes)	MP 54.10 WB	13:32:00	Actual: 0.35 Hours		1973							
	Debris	1.05	9/10/2047	Reqd: 1 Hours									
GP 1.1	(Cleared Gutter from	I-25 MP 216.50	8/10/2017 17:09:00	Respd: 8/10/2017 17:50	N/A	N/A							
	lanes)	UC.01 2 TVIF	17.09:00	Actual: 0.68 Hours									

The table below provides a listing of items recorded this month:





Element	Decorintion	Location	DDS Notified	C-1	Category 2			
Category	Description	Location	BRS Notified	Categ Hazard Mitigation	Permanent Repair			
	Debris			Read: 1 Hours	Permanent Remedy	Fermanent Kepan		
GP 1.1	(Cleared Tire from	US36	8/10/2017	Respd: 8/10/2017 11:32	N/A	N/A		
GP 1.1		MP 55.60 WB	11:27:00	•	N/A	IN/A		
	lanes)			Actual: 0.08 Hours				
0044	Debris	US36	8/10/2017	Reqd: 1 Hours				
GP 1.1	(Cleared Mattress from	MP 45.00 WB	13:52:00	Respd: 8/10/2017 13:59	N/A	N/A		
	lanes)			Actual: 0.11 Hours				
	Debris	US36	8/10/2017	Reqd: 1 Hours				
GP 1.1	(Cleared Pallet from	MP 40.10 WB	12:08:00	Respd: 8/10/2017 12:18	N/A	N/A		
	lanes)	WI 40.10 WB	12.00.00	Actual: 0.16 Hours				
	Debris	US36	8/16/2017	Reqd: 1 Hours				
GP 1.1	(Cleared Tire from	MP 42.10 WB	18:42:00	Respd: 8/16/2017 19:05	N/A	N/A		
	lanes)	WF 42.10 WD	10.42.00	Actual: 0.38 Hours				
	Debris	11000	0/40/0047	Regd: 1 Hours				
GP 1.1	(Reported Debris,	US36	8/16/2017	Respd: 8/16/2017 20:07	N/A	N/A		
	Nothing Found)	MP 56.00 EB	19:44:00	Actual: 0.38 Hours				
	Graffiti				Reqd: 10 Days			
GP 12.1	(Removed Graffiti from	US36	8/17/2017	N/A	Respd: 8/17/2017 16:00	N/A		
1 12.1	•	MP 57.10 EB	12:15:00	N/A		11/7		
	Barrier)			Dords 1 Laura	Actual: 0.15 Days			
0044	Debris	US36	8/17/2017	Reqd: 1 Hours	N 1/2	L 1/A		
GP 1.1	(Cleared Metal from	MP 40.00 EB	07:00:00	Respd: 8/17/2017 07:30	N/A	N/A		
	lanes)			Actual: 0.50 Hours				
	Debris	US36	8/20/2017	Reqd: 1 Hours				
GP 1.1	(Cleared Mattress from	MP 40.40 EB	15:26:00	Respd: 8/20/2017 16:05	N/A	N/A		
	lanes)	WF 40.40 ED	15.20.00	Actual: 0.65 Hours				
	Debris	US36	0/04/0047	Regd: 1 Hours				
GP 1.1	(Cleared Slide from		8/21/2017	Respd: 8/21/2017 14:30	N/A	N/A		
	lanes)	MP 53.70 EB	13:48:00	Actual: 0.70 Hours				
	Debris			Regd: 1 Hours				
GP 1.1	(Cleared Fireworks from	US36	8/23/2017	Respd: 8/23/2017 16:30	N/A	N/A		
GF 1.1	`	MP 52.00 EB	16:02:00	Actual: 0.46 Hours	N/A	IN/A		
	lanes)							
0044	Debris	US36	8/25/2017	Reqd: 1 Hours	N 1/A	b 1/A		
GP 1.1	(Cleared Rebar from	MP 56.40 EB	19:30:00	Respd: 8/25/2017 20:00	N/A	N/A		
	lanes)			Actual: 0.50 Hours				
	Incident Response	US36	8/26/2017	Reqd: 24 Hours				
GP 13.1	(Responded to Bridge	MP 55.94 EB	08:03:00	Respd: 8/26/2017 08:42	N/A	N/A		
	Joint Damage)	WI 30.34 ED	00.00.00	Actual: 0.65 Hours				
	Debris	US36	8/26/2017	Reqd: 1 Hours				
GP 1.1	(Cleared Wood from	MP 51.80 WB		Respd: 8/26/2017 22:00	N/A	N/A		
	lanes)	IVIP 31.00 WD	21:30:00	Actual: 0.49 Hours				
	Debris	11000	0/07/0017	Reqd: 1 Hours				
GP 1.1	(Cleared Tire from	US36	8/27/2017	Respd: 8/27/2017 02:40	N/A	N/A		
	lanes)	MP 50.40 WB	02:00:00	Actual: 0.66 Hours				
	Debris			Regd: 1 Hours				
GP 1.1	(Cleared Wood from	US36	8/27/2017	Respd: 8/27/2017 15:45	N/A	N/A		
51 1.1	lanes)	MP 51.20 WB	15:30:00	Actual: 0.24 Hours	17/7	11/7		
	/							
00424	Incident Response	US36	8/27/2017	Reqd: 24 Hours	NI/A	N1/A		
GP 13.1	(Responded to Bridge	MP 55.94 EB	12:014:00	Respd: 8/27/2017 12:57	N/A	N/A		
	Joint Damage)			Actual: 0.72 Hours				
	Debris	US36	8/27/2017	Reqd: 1 Hours				
GP 1.1	(Cleared Cone from	MP 56.50 WB	23:30:00	Respd: 8/28/2017 00:15	N/A	N/A		
	lanes)	WI 00.00 WB	20.00.00	Actual: 0.75 Hours				
	Debris	US36	8/30/2017	Reqd: 1 Hours				
GP 1.1	(Cleared Clothes from			Respd: 8/30/2017 16:30	N/A	N/A		
	lanes)	MP 43.20 WB	15:37:00	Actual: 0.88 Hours				
	Debris		a/a./	Regd: 1 Hours				
GP 1.1	(Reported Debris,	I-25	8/31/2017	Respd: 8/31/2017 14:30	N/A	N/A		
5, 1.1	Nothing Found)	MP 212.80	14:10:00	Actual: 0.33 Hours	17/7	11/7		
	Nothing Found)	US36		Adual 0.00 Hours		Regd: 28 Days		
CD 10 4	Vegetation Control		8/31/2017	NI/A	NI/A			
GP 10.1	(Mowing)	MP54.8-57.3	08:00:00	N/A	N/A	Respd:		
		EB&WB				Actual: In Progress		

All items were completed within the required response time. Items that are *In Progress* are still within the allowed response time.

F. Detailed Results of All Inspections, Assessments, and Testing Activities

During this reporting period there were no special inspections, assessments, or testing results outside normal operating condition.





G. Monthly Toll System Performance Reports

Toll system operated within proposed parameters per Broadspectrum's observations.

H. Preventative Maintenance Plan and Progress

Preventative Maintenance work is contingent on Initial Works Package implementation.

I, J. Mean Time between Failure (MTBF), Mean Time To Repair (MTTR)

No Maintained Elements experienced a failure type breakdown this month. Broadspectrum considers a breakdown to be a failure when the element cannot be used for its intended purpose until repaired.