October 2019 Monthly Operations Report











Table of Contents

1.0	Volumes and Lane Usage	3
2.0	Revenues	5
3.0	Operational Incidents, Issues, and Closures	5
4.0	Mean Time Between Failure (MTBF) and Mean Time to repair (MTTR)	7
5.0	Hybrid Utilization	7
TABL	LES	
Table	e 1 – Monthly Traffic Summaries	4
Table	e 2 – Managed Lanes Closures to Date	6
Table	e 3 – ETCS Issues per CA Schedule 6 Appendix 6-2	7
Table	e 4 - Status of Noncompliance Categories	7
Table	e 5 – Mean Time Between Failure & Mean Time To Repair	7
Table	e 6 – Hybrid Utilization	8
FIGU	JRES	
Figur	re 1 – Monthly Traffic Distribution	4
Figur	re 2 – Daily Traffic Counts	5





INTRODUCTION

Pursuant to Schedule 6, Section 1.8.2(a) of the Concession Agreement, Plenary Roads Denver ("PRD") is required to submit a monthly report covering all essential statistics related to the Managed Lanes. The following data covers the month of October 2019. Operationally, October was a positive month. Several routine maintenance tasks were completed, there were minimal incidents to maintained elements, and traffic volumes were consistent with expectations.

1.0 VOLUMES AND LANE USAGE

Over the last several months as more commuters use the transponders for either ExpressToll™ (AVI) or HOV travel, License Plate (LPT) transactions have consistently decreased as a percentage of total traffic volume. The total monthly gantry traffic volume for October 2019 in the I-25 Central and US 36 Managed Lanes was 312,806 and 1,565,965, respectively.

The table below provides the monthly summary for each Managed Lanes roadway, along with a detailed breakdown of weekday volumes. For reference, the AM Peak Period is considered to be weekdays from 6:45 am – 8:45 am. The PM Peak Period is considered to be, weekdays, from 4:15pm – 5:45pm. It should be noted, that the I-25 Managed Lane traffic reflects traffic counts from a single gantry and US 36 Managed Lane counts reflect fourteen gantries, seven gantries in each direction. Therefore, US 36 data will indicate far greater traffic counts that are not comparative to those of I-25.

The following charts depict the distribution of traffic by type (Figure 1) and the daily traffic counts (Figure 2) and for the month.


	Traffic	Summary ((US 36)									
Non-Rev & AVI LPT HOV Hybrid Total												
Total Monthly Traffic	869,642	402,233	254,427	39,663	1,565,965	2,605						
Maximum Weekday Traffic	45,330	23,510	14,014	1,817	83,478	157						
Average Weekday Traffic	33,972	14,799	8,270	1,599	58,640	97						
Average Hourly AM Peak Traffic	4,828	1,821	952	205	7,806	N/A						
Average Hourly PM Peak Traffic	4,870	1,929	1,068	183	8,050	N/A						





	Traff	ic Summary	(I-25C)			
	Non-Rev & Hybrid	Total	Hybrid			
Total Monthly Traffic	152,716	92,972	55,441	11,677	312,806	802
Maximum Weekday Traffic	7,870	4,869	2,428	515	15,446	46
Average Weekday Traffic	6,166	3,728	2,039	474	11,933	33
Average Hourly AM Peak Traffic	800	565	286	61	1,651	N/A
Average Hourly PM Peak Traffic	746	423	249	65	1,418	N/A

Table 1 - Monthly Traffic Summaries







Figure 1 – Monthly Traffic Distribution










Figure 2 - Daily Traffic Counts

2.0 REVENUES

During the month of October 2019, PRD collected \$898,221 and \$929,972 from users of the I-25 Central and US36 Managed Lanes, respectively. For purposes of this report, revenues are recognized at the time of collection, which is typically sometime after they have been incurred for those customers who are billed based on their license plate. For example, if a single-occupant vehicle uses the lanes in October but pays in January, the associated revenue is attributed to January.

3.0 OPERATIONAL INCIDENTS, ISSUES, AND CLOSURES

The project had numerous routine debris removals, lighting incidents, guardrail incidents, sign incidents, and graffiti control during the month. The routine lighting, guardrail, roadway markings and sign incidents are all planned for repair within the allowable response period and several previously identified lighting incidents were repaired. All incidents were responded to and rectified within the allowable timeframes.

The week of July 9, 2019, there was a pavement defect noted that was progressing in severity near the Church Ranch Blvd. Interchange affecting US36 mainline in the eastbound direction. After further site investigation by CDOT, HPTE, PRD and Ferrovial Services, it was decided that the roadway should be closed on July 12, 2019. In order to facilitate traffic movement, the eastbound lanes were placed in the westbound direction. The final configuration of traffic required a closure of the EB and WB Promenade toll point. The lanes were restored to their original configuration and operation on October 4, 2019. There were subsequent closures in October that were limited to night work to access work areas to complete.





Date	Start	Stop	Duration
July 5, 2019	15:42	16:27	0:45
July 9, 2019	17:30	18:15	0:45
July 10, 2019	13:35	14:32	0:57
July 12, 2019 - October 4,	19:15	05:00	2,145:45
2019			(89 Days 9 Hours and 45 Minutes)
July 25, 2019	08:57	10:10	1:13
August 1, 2019	15:42	16:55	1:13
August 12, 2019	08:02	08:54	0:52
August 12, 2019	18:36	19:01	0:25
August 15, 2019	15:46	16:17	0:31
August 16, 2019	05:46	07:36	1:50
August 23, 2019	08:22	09:21	0:59
August 26, 2019	15:50	16:32	0:42
September 3, 2019	07:46	08:17	0:32
September 13, 2019	15:48	16:30	0:42
September 16, 2019	12:50	13:27	0:37
October 3, 2019	06:48	07:21	0:33
October 4, 2019	07:40	08:14	0:34
October 10, 2019	10:00	11:48	1:48
October 10, 2019	10:33	11:18	0:45
October 15, 2019	09:06	09:43	0:37
October 21, 2019	16:03	17:39	1:36
October 21, 2019	16:46	18:14	1:28
October 28, 2019	06:00	06:45	0:45
October 30, 2019	09:41	10:25	0:44
October 31, 2019	16:03	17:39	1:36
Total			2,168 hours 14 minutes
Remaining Closure Hours Available (Ref: CA 29.7)			0 hours 0 minutes

Table 2 – Managed Lanes Closures to Date





The table below provides a listing of ETCS items recorded this month, consistent with Appendix 6-2 of Schedule 6.

Element ID	Cat	Element	Performance Item	PRD Notified	Contractual Cure Period	Cure Achieved
None						

Table 3 – ETCS Issues per CA Schedule 6 Appendix 6-2

The table below provides a status of all Noncompliance categories in accordance with paragraph 1.2 of Schedule 10.

con	Non- npliance ocation	Nature	Cause	Cure Date	Uncured Non- compliance Point	Unexpired Non- compliance Point	365 Day Expiration Date	1095 Day Expiration Date
- 1	None							

Table 4 – Status of Noncompliance Categories

4.0 MEAN TIME BETWEEN FAILURE (MTBF) AND MEAN TIME TO REPAIR (MTTR)

Mean Time Between Failure (MTBF) and Mean Time To Repair (MTTR) data is provided in the table below. Only Maintained Elements that were repaired during the reporting period and had a failure type breakdown are listed in the table. We consider a breakdown to be a failure when the element cannot be used for its intended purpose until repaired.

Maintained Element	Mean Time Between Failure (MTBF) (Hours)	Mean Time To Repair (MTTR) (Hours)
None	N/A	N/A

Table 5 – Mean Time Between Failure & Mean Time To Repair

5.0 HYBRID UTILIZATION

Total Hybrid Trips





I-25 Central	802
US 36	2,605

Table 6 – Hybrid Utilization

Fuel-efficient "Hybrid" vehicles are permitted to access the Express Lanes free of charge, regardless of occupant numbers, provided that they have obtained a permit from CDOT, obtained a Hybrid transponder from E-470, and display an E-470 Hybrid decal on the vehicle's windshield.





OPERATIONS AND MAINTENANCE MONTHLY REPORT OCTOBER 2019

US 36 and I-25 Express Lanes Project



Plenary Roads Denver, LLC 1700 Lincoln Street, Suite 3000 Denver, CO 80203

Attention: Mr. Christian Guevara, PE



Prepared By:

Ferrovial Services 10525 West 120th Avenue Broomfield, CO 80021 United States of America

Justin Doles, PE Project Manager





OPERATIONS AND MAINTENANCE – MONTHLY REPORT OCTOBER 2019 US 36 and I-25 Express Lanes Project

Revision	Date	Approved
Rev. 0	11/08/2019	Just Dla

This report titled *Operations and Maintenance Monthly Report, October 2019* has been prepared by Ferrovial Services for the exclusive use of Plenary Roads Denver, LLC (PRD). No other party is an intended beneficiary of this report or the information, opinions, and conclusions contained herein. Any use by any party other than PRD of any of the information, opinions, or conclusions is the sole responsibility of said party. The use of this report shall be at the sole risk of the user regardless of any fault or negligence of PRD or Ferrovial Services.

The information and analyses contained herein have been completed to a level of detail commensurate with the objectives of the assignment and in light of the information made available to Ferrovial Services at the time of preparation. This report and its supporting documentation have been reviewed and/or checked for conformance with industry-accepted norms. To the best of the information and belief of Ferrovial Services, the information presented in this report is accurate to within the limitations specified herein.

This report is Ferrovial Services pdf file: OM Monthly Report October 2019.pdf. Any reproductions or modifications of this report are uncontrolled and may not be the most recent revision.





The O&M Monthly Report contains all relevant information for the month of October 2019. Ferrovial Services continues ongoing and preventive maintenance activities for the I-25 and US36 Managed Lanes Project.

Ferrovial Services Commitment to Safety

Ferrovial Services conducted weekly toolbox talk meetings during the month. The purpose of the tool box talks is to cover important safety items that relate to the project such as near misses, "better ways" as to how safety is conducted for the Project, and discussion on safety procedures for maintenance activities. In addition to the toolbox talks, Ferrovial Services conducts a weekly progress meeting. This is a forum for feedback from staff on Operations, Incident Response, and Maintenance activities.

Toolbox Talks this month included:

- Fatigue
- Evacuation Plans
- Evacuation Emergencies
- Scene Safety
- Weather and National Disasters

A. Summary of the Planned Maintenance Activities for the Upcoming Month – November 2019

Ferrovial Services has identified the upcoming planned maintenance activities as described in Table 1.7.1.3 of The Maintenance Management Plan. These activities include preventative and routine maintenance in order to successfully operate and maintain the Project. A listing of the planned maintenance activities for the month of November 2019 is included below.





FIG. A-1 Planned Maintenance Activities for November 2019

X – *Indicates the day the task is planned.*

Performance Standard Identification	Work Activity-	Frequency															Nov	/-19														
Number (Table	Description		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
6.1)			F	S	S	M	Т	W	Т	F	S	S	M	Т	W	Т	F	S	S	М	Т	W	Т	F	s	S	М	Т	W	Т	F	s
ML-1	MAINTENANCE PATROL	Daily	х			х	х	х	х	х			х	х	х	х	х			х	х	х	х	х			х	х	х			
ML-1	FLEXIBLE PAVEMENT OBSERVATION / REPAIR	F-52				х							х							х							х					
ML-1	RIGID PAVEMENT OBSERVATION / REPAIR	F-52				х							х							x							x					
ML-4	DELINEATORS & MARKERS OBSERVE / CLEAN / REPAIR	F-12												x																		
ML-2	DRAINAGE (INLET) OBSERVE/ CLEAN / REPAIR	F-12												х																		
ML-2	DRAINAGE (PIPE/CULVERT) OBSERVE / CLEAN / RPR	F-12												х																		
ML-5.1	GUARDRAIL, SAFETY BARRIER								х																							
ML 5.2	IMPACT ATTENUATORS								х																							
ML-6	SIGN CLEANING	F-1													х	х																
ML-6	SIGN OBSERVATION / REPAIR	F-52				х							х							х							х					
ML-8	ELECTRICAL SUPPLY INSPECTION / REPAIR	F-12											х																			
ML-8	ACCESS PANEL OBSERVATION / REPAIR	F-12											х																			
ML-10	HERBICIDE & WEED CONTROL MAINTENANCE	F-52	х							х							x							x								
ML-12	GRAFFITI OBSERVATION / REMOVAL	F-52						х							х							x						х				
ML-14	MECHANICAL ROAD SWEEPING	F-12																		х	х	х	х									
ML-14	LITTER OBSERVATION / REMOVAL	Daily	х			х	х	х	х	х			х	х	х	х	х			х	х	х	х	х			х	х	х			
ML-15	NODE BUILDING 2 MAINTENANCE	F-1								х																						
ML-15	SAND STORAGE DOME MAINTENANCE	F-1								х																						
ML-15	LIQUID STORAGE FACILITY MAINTENANCE	F-1								х																						
	REVERSIBLE LANE OPERATIONS	Daily	х			х	х	х	х	х			х	х	х	х	х			х	х	х	х	х			х	х	х		х	
	GATE MAINTENANCE & REPAIR	_				х							х							х							х					

Frequency of Activity:

Daily – Daily Activity F-4 – Quarterly Activity F-52 – Weekly Activity F-2 – Semi-Annual Activity

F-12 – Monthly Activity F-1 – Annual Activity







B. Summary of Performed and Completed Maintenance Activities

Fig. B-1 Performed and Complete Maintenance Activities for October 2019

X Indicates the day of the month that the task was completed.

Performance Standard Identification	Work Activity-	Frequency	Oct-19																														
Number (Table	Description		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
6.1)			Т	w	Т	F	S	S	М	Т	w	Т	F	S	S	М	Т	w	Т	F	S	S	М	Т	W	Т	F	S	S	М	Т	w	Т
ML-1	MAINTENANCE PATROL	Daily	X	X	X	X			X	X	X	X	X			X	X	X	X	X			X	X	X	X	X			X	X	X	X
	FLEXIBLE PAVEMENT OBSERVATION / REPAIR	F-52	x						X							X							x							x			
	RIGID PAVEMENT OBSERVATION / REPAIR	F-52	x						x							X							х							x			
	DELINEATORS & MARKERS OBSERVE / CLEAN / REPAIR	F-12																	x														
	DRAINAGE (INLET) OBSERVE/ CLEAN / REPAIR	F-12										x																					
	DRAINAGE (PIPE/CULVERT) OBSERVE / CLEAN / RPR	F-12										x																					
ML-3	BRIDGE JOINT & SEAL	BI-ANNUAL														x	x	x	x	x			х	x	x	x	x			x	x	x	x
ML-3.2	BRIDGE DRAINAGE SYSTEM MAINTENANCE	BI-ANNUAL							x	x																							
	GUARDRAIL, SAFETY BARRIER								x																								
ML 5.2	IMPACT ATTENUATORS								x																								
	SIGN OBSERVATION / REPAIR	F-52		x						x							x							x							x		
	STREET LIGHTING OBSERVATION / REPAIR	F-52		x							x							x							x							x	
ML-8	ELECTRICAL SUPPLY INSPECTION / REPAIR	F-12									x																						
ML-8	ACCESS PANEL OBSERVATION / REPAIR	F-12									x																						
	HERBICIDE & WEED CONTROL MAINTENANCE	F-52				х							x							x							x						
ML-12	GRAFFITI OBSERVATION / REMOVAL	F-52	x						x							x							х							x			
ML-14	MECHANICAL ROAD SWEEPING	F-12														X	x	X	X														
ML-14	LITTER OBSERVATION / REMOVAL	Daily	x	x	x	х			x	x	x	x	x			X	x	x	x	x			х	x	x	x	x			x	x	x	x
	NODE BUILDING 2 MAINTENANCE	F-1											x																				
ML-15	SAND STORAGE DOME MAINTENANCE	F-1											х																				
	LIQUID STORAGE FACILITY MAINTENANCE	F-1											х																				
	REVERSIBLE LANE OPERATIONS	Daily	x	x	x	x			x	x	x	x	х			x	x	x	x	x			x	x	х	x	x			x	x	x	x
	GATE MAINTENANCE & REPAIR		x						x							x							x							x			







Fig. B-2 Work Accomplished This Month

Activity	Actual Work
102 Patrolling and Inspect (HR)	23.31
152 Flex Patch /Minor Repairs (SY)	2
153 Concrete Pave Surface Rpr (SY)	1.5
156 HandCrack Seal Flex Pave(GAL)	17421
157 Hnd Crck Seal Rigid Pave (LF)	10.5
162 Surface Shldr Rprs (SY)	1050
210 Slope Repairs (CY)	77
215 Roadkill Cleanup (EA)	5
218 Litter Removal (CY)	42.5
218 Debris in Roadway (HR)	5
221 Sweeping Disposal (TON)	14
222 Sweeping (MI)	116
254 Veg Cntrl Hnd/Chem (HR)	8
301 Sign Maintenance (EA)	3
307 Direct Gate Maint (EA)	1
314 Reversible Lane Operations	322
329 Courtesy Assistance (HR)	330
353 Bridge Maintenance Sealing (SY)	9338.2
364 Bridge Joint Mnt Cln/Rpr (LF)	50
402 Snow Plow & Material (MI)	598
540 Graffiti Removal (SF)	50

C. Summary of Planned Maintenance that was Not Completed for the Month

Ferrovial Services completed all scheduled maintenance activities for the period of October. Frequencies and/or actual date of the month of some activities may have been adjusted based on actual conditions.

D. Summary of the Maintenance Activities and Results Performed for the Month Beyond Planned Maintenance

A summary of unplanned maintenance activities provided below:

Snow and Ice Control:

Precipitation Event Start		Equipment Deployed		Precipitation Event End		Service Level "A" Achieved in ML		Service Level "B" Achieved in GP	
10/10/2019	6:42	10/9/2019	23:30	10/10/2019	18:35	10/10/2019	10:38	10/10/2019	10:38
10/23/2019	21:20	10/23/2019	19:10	10/24/2019	9:50	10/24/2019	2:15	10/24/2019	2:15
10/27/2019	1:10	10/26/2019	23:00	10/30/2019	11:40	10/30/2019	6:15	10/30/2019	6:15

Courtesy Patrol: None

Hazardous Materials Incidents: None







E. Operating Contractor's Incident Response Logs Related to Maintenance Activities

This section provides a summary of Ferrovial Services performance related to the Performance and Measurement Criteria listed in Appendix 6-1.1 of the Operating Contract.

The table below provides a listing of items recorded this month:

Element	Description	Location	Notified	Response to Defects			
Category	•			Cate	Category 2		
				Hazard Mitigation	Permanent Remedy	Permanent Repair	
GP5.1	Barrier (Impact Damage)	MP 57.1 WB	6/4/2019 08:20:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML5.2	Attenuator (Impact Damage)	MP 56.1 EB	6/13/2019 06:40:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
GP5.1	Guardrail (Impact Damage)	MP 54.4 WB	7/17/2019 00:30:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (W Out)	040-U36-LHT- 0210, MP 56.6	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0090, MP 55.9	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (S Out)	040-U36-LHT- 0230, MP 56.7	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0080, MP 55.8	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0070, MP 55.8	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0060, MP 55.7	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0050, MP 55.6	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0150, MP 56.2	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-l25-LHT- 0110, MP 215.1	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (SE Out)	040-I25-LHT- 0070, MP 214.8	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (N Out)	040-U36-LHT- 0240, MP 56.8	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (East Out)	040-U36-LHT- 0190, MP 56.5	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0130, MP 56.1	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (EW Out)	040-U36-LHT- 0180, MP 56.4	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	
ML8.1	Lighting (All Out)	040-U36-LHT- 0140, MP 56.2	9/3/2019 21:00:00	N/A	N/A	Reqd: 6 Months Respd: Actual: In Progress	





Category Category	Element	Description	Location	Notified	Response to Defects			
Max	Category	·			Categ	Category 2		
M.B.2								
M.B.2		Lighting	040-20S-LHT-	0/4/2010			Reqd: 6 Months	
Mail	ML8.2		0005-SGN_LHT-		N/A	N/A	Respd:	
M.B.2		(Out)	03, MP 0.5	21.00.00				
MBL2		Lighting	040-20S-LHT-	9/4/2019			Reqd: 6 Months	
GP8.2 Lighting OB-USS-CHT OS-S-SQN_LHT OS-SQN_LHT OS-S-SQN_LHT OS-SQN_LHT OS-SQN_LHT	ML8.2		0005-SGN_LHT-		N/A	N/A		
Columbia Columbia		(Out)		21.00.00				
Columber Columber		Lighting		9/4/2019				
Columber Columber	GP8.2		_		N/A	N/A		
Company Comp		(Culy		21.00.00				
GP8.2 Gout County Coun		Lighting		9/4/2019			·	
Color	GP8.2		_		N/A	N/A		
GP8.2 Lighting Q040-U364-HT Q147 P5.00 Q140-U364-HT Q2, MP 56.0 Q2-U360-HT Q2, MP 56.0 Q2-U365-HT Q2, MP 56.0 Q2-U365-HT Q2, MP 56.0 Q369-S0N_LHT Q2, MP 56.0 Q40-U364-HT Q44-U319 Q44-U319		(0 11)		21.00.00				
GP6.2 Count		Lighting		9/4/2019			· ·	
Colored Debris From Lanes Colored Prom Lanes Colored Debris From Lanes Colored Prom Lanes Colored Debris From Lanes Colored Prom Lanes Colored	GP8.2	0 0	_		N/A	N/A		
GP8.2 Lighting Qu Qu Qu Qu Qu Qu Qu Q		(,						
Country Coun		Lighting		9/4/2019				
MLB.2 Lighting	GP8.2		_	21:00:00	N/A	N/A	•	
MLB.2 Country Countr		` '						
Color		Lighting		9/4/2019	N/A	A1/A	•	
Sign	ML8.2			21:00:00	N/A	N/A		
College			01, MP 0.5					
Compact Damage Comp	CDC 4	Sign	MD 40 C M/D	9/11/2019	N1/A	N1/A	•	
Sign (Impact Damage)	GP6.1	(Impact Damage)	IVIP 42.0 VVB	19:15:00	IVA	IVA	·	
College								
Ceared Debris Celeared Debris From Lanes MP 57.1 EB 10/26/2019 Respd: 10/26/2019 17:00 Actual: 0.70 Hours Respd:	CDC 1	Sign	MD 47 2 ED	9/26/2019	NI/A	NI/A		
Debris Cleared Debris From Lanes MP 57.1 EB 10/26/2019 16.18:00 Respd: 10/26/2019 17:00 Actual: 0.70 Hours Respd: 10/26/2019 17:00 Actual: 0.70 Hours Respd:	GF 0.1	(Impact Damage)	IVIF 47.3 EB	22:49:00	IVA	IVA	·	
Cleared Debris From Lanes MP 57.1 EB 10/28/2019 16:18:00 Actual: 0.70 Hours N/A N/A N/A Regd: 6 Months Respd: 10/27/2019 N/A N/A Regd: 6 Months Respd: 6 Months Re					Pead: 1 Hours		Actual. III Flogress	
Cleared Debris From Lanes Sign Sign (Impact Damage) MP 49.1 WB 10/27/2019 02:41:00 N/A N/A Regd: 6 Months Respd: Actual: in Progress Regd: 6 Months Respd: Actual: in Progress Regd: 6 Months Respd: Actual: in Progress Regd: 6 Months Respd: 10/30/2019 N/A N/A Respd: 10/30/2019 Regd: 1 Hours Respd: 10/30/2019 12:22:00 Regd: 1 Hours Respd: 10/20/2019 Respd: 10/20	GP1 1		MP 57 1 FR			N/A	N/Δ	
Sign (Impact Damage)	O. 1.1	(Cleared Debris From Lanes)	Wii 07.1 LD	16:18:00	1	1471	1071	
GP6.1 Sign (Impact Damage) MP 49.1 WB 02:41:00 N/A N/A Respd:		0.					Read: 6 Months	
Collaboration Collaboratio	GP6.1		MP 49.1 WB		N/A	N/A		
Sign (Impact Damage)		(Impact Damage)		02:41:00			· ·	
MP 48.05 EB 16:00:00		Cian		10/20/2010			Reqd: 6 Months	
ML1.1 Debris (Cleared Ladder From Lanes) MP 53.0 WB 10/20/2019 12:22:00 Actual: 0.88 Hours N/A N/A	GP6.1		MP 48.05 EB		N/A	N/A	Respd: 10/30/2019 22:45	
ML1.1 (Cleared Ladder From Lanes) MP 53.0 WB 10/20/2019 12:22:00 Respd: 10/20/2019 13:15 Actual: 0.88 Hours Reqd: 1 Hours Respd: 10/22/2019 08:50:00 Respd: 10/22/2019 09:09 Actual: 0.31 Hours Respd: 10/16/2019 17:56:00 N/A N/A N/A N/A Respd: 10/16/2019 17:50:00 Respd: 10/16/2019 11:18 N/A N/A Respd: 10/16/2019 11:18 Actual: 0.31 Hours Respd: 10/16/2019 11:42:00 Respd: 10/16/2019 11:42:00 Respd: 10/16/2019 11:42:00 Respd: 10/25/2019 Respd: 10/25/2019 Respd: 10/25/2019 Respd: 10/25/2019 11:42:00 Respd: 10/16/2019 11:42:00 Respd: 10/16/2019 11:42:00 Respd: 10/16/2019 11:18 Respd: 10/16/2019 Respd: 10/16/2019 11:42:00 Respd: 10/16/2019 Respd: 10/16/2019 11:42:00 Respd: 10/16/2019 Respd: 10/16/2019		(Impact Damage)		16.00.00			Actual: 0.01 Months	
MR MR MR MR MR MR MR MR	·	Debris		10/20/2010	Reqd: 1 Hours			
Cleared Carcass From Lanes Cleared Carcass From Lanes Cleared Pipe From Lanes MP 39.4 EB 10/30/2019 10/30/2019 10/30/2019 10/30/2019 10/25/2019 10/25/2019 10/30/2019	ML1.1	(Cleared Ladder From	MP 53.0 WB		Respd: 10/20/2019 13:15	N/A	N/A	
GP1.1 (Cleared Carcass From Lanes)				12.22.00				
Cleared Carcass From Lanes MP 46.2 EB 08:50:00 Respc: 10/22/2019 09:09 Actual: 0.31 Hours Respc: 10/15/2019 17:30 Actual: 0.31 Hours				10/22/2019	· · · · · · · · · · · · · · · · · · ·			
Canes Cane	GP1.1	•	MP 46.2 EB		1	N/A	N/A	
Cleared Pipe From Lanes MP 39.4 EB 10/14/2019 17:56:00 N/A Respd: 10/15/2019 17:30 Actual: 0.03 Months		Lanes)			Actual: 0.31 Hours			
MI		Sian		10/14/2019				
ML1.1 Debris (Cleared Pipe From Lanes) MP 39.4 EB 10/16/2019 10:59:00 Respd: 10/16/2019 11:18 Actual: 0.31 Hours Respd: 10/16/2019 Respd: 10/25/2019 12:21 Actual: 10 Progress MP 56.9 EB 10/25/2019 11:42:00 Respd: 10/25/2019 12:21 Actual: 0.64 Hours Respd: 10/16/2019 11:18 Actual: 0.31 Hours Respd: 10/18/2019 09:33 Actual: 0.51 Hours Respd: 10/18/2019 09:33 Actual: 0.51 Hours Respd: 10/18/2019 09:33 Actual: 0.51 Hours Respd: 10/18/2019 09:35 Respd: 10/11/2019 05:35 N/A	GP6.1		MP 39.4 EB		N/A	N/A		
ML1.1 Debris (Cleared Pipe From Lanes) MP 39.4 EB 10/16/2019 10:59:00 Respd: 10/16/2019 11:18 N/A N/A N/A Reqd: 6 Months Respd: Actual: 0.31 Hours N/A N/A Respd: Actual: In Progress N/A N/A N/A Respd: Actual: In Progress N/A N/		(1 3 3 3 3 7			5		Actual: 0.03 Months	
MELT.1 (Cleared Pipe From Lanes)		Debris		10/16/2019				
Sign (Impact Damage)	ML1.1		MP 39.4 EB			N/A	N/A	
Cleared Pipe From Lanes MP 46.1 WB		, , ,			Actual: 0.31 Hours		D 1011	
Cleared Tire From Lanes MP 56.9 EB 10/25/2019 11:42:00 Regd: 1 Hours Respd: 10/25/2019 12:21 Actual: 0.64 Hours Respd: 10/16/2019 10:59:00 Regd: 1 Hours Respd: 10/16/2019 11:18 N/A	CDC 4	Sign	MD 4C 4 W/D	10/30/2019	NI/A	NI/A		
Debris (Cleared Tire From Lanes)	GP6.1	(Impact Damage)	WP 46.1 WB	16:00:00	IN/A	IV/A	· ·	
Cleared Tire From Lanes MP 56.9 EB 10/25/2019 12:21 Actual: 0.64 Hours Respd: 10/25/2019 12:21 Actual: 0.64 Hours Respd: 10/16/2019 10:59:00 Respd: 10/16/2019 11:18 N/A N/A N/A N/A Respd: 10/16/2019 10:59:00 Respd: 10/16/2019 11:18 N/A N/A N/A Respd: 10/16/2019 11:18 N/A N/A N/A Respd: 10/16/2019 11:18 N/A N/A N/A Respd: 10/16/2019 11:18 N/A N/A N/A N/A N/A N/A N/A N/A Respd: 10/16/2019 11:18 N/A N/					Pond: 1 Hours		Actual: In Progress	
Cleared From Lanes Cleared From Lanes Cleared Pipe From Lanes MP 39.4 EB 10/16/2019 10/59:00 Regd: 1 Hours Respd: 10/16/2019 11:18 N/A N/A N/A Regd: 1 Hours Regd: 10/18/2019 09:33 Actual: 0.51 Hours Regd: 1 H	CD1 1	Debris	MD 56 0 ED	10/25/2019		N/A	NI/A	
Debris (Cleared Pipe From Lanes)	GP 1.1	(Cleared Tire From Lanes)	IVIP 30.9 EB	11:42:00		IN/A	IVA	
Cleared Pipe From Lanes MP 39.4 EB 10/16/2019 Respd: 10/16/2019 11:18 N/A N/A							1	
Cleared Pipe From Lanes 10:59:00 Actual: 0.31 Hours	GD1 1		MD 30 4 ED		· · · · · · · · · · · · · · · · · · ·	NI/A	NI/A	
Debris (Cleared Carcass From Lanes)	GP 1.1	(Cleared Pipe From Lanes)	IVIF 39.4 EB	10:59:00	1	IV/A	IVA	
GP1.1 (Cleared Carcass From Lanes) MP 49.8 WB 10/18/2019 09:02:00 Respd: 10/18/2019 09:33 Actual: 0.51 Hours N/A N/A Debris Debris Regd: 1 Hours Regd: 1 Hours ML1.1 (Cleared Cylinder From MP 213.5 NB 05:39:00 10/11/2019 05:55 N/A Respd: 10/11/2019 05:55 N/A		Dobrio					-	
Lanes 09:02:00 Actual: 0.51 Hours	GD1 1		MD 40 0 W/D		· · · · · · · · · · · · · · · · · · ·	NI/A	NI/A	
Debris	GF 1.1	,	IVIF 43.0 VVD	09:02:00	1	IN/A	IWA	
ML1.1 (Cleared Cylinder From MP 213.5 NB 10/11/2019 Respd: 10/11/2019 05:55 N/A N/A							<u> </u>	
1 ' '	MI 1 1		MP 213.5 NR		· · · · · · · · · · · · · · · · · · ·	N/A	N/A	
	.v 1 . 1	Lanes)	2.0.0.40	05:39:00	Actual: 0.26 Hours	14/1	1 1 1 1	





Response to Defects Element Location Notified Description Category Category 1 Category 2 Permanent Repair **Hazard Mitigation** Permanent Remedy Read: 1 Hours Debris 10/14/2019 **GP1.1** MP 44 WB Respd: 10/14/2019 12:04 N/A N/A (Cleared Debris From Lanes) 11:41:00 Actual: 0.38 Hours Reqd: 10 Days Graffiti 10/3/2019 GP12.1 MP 55.9 WB Respd: 10/4/2019 13:17 N/A N/A (Removed Graffiti) 15:13:00 Actual: 0.91 Days Reqd: 1 Hours 10/1/2019 Debris GP1.1 MP 50.0 EB N/A Respd: 10/1/2019 13:38 (Cleared Carpet From Lanes) 13:22:00 Actual: 0.26 Hours Debris Read: 1 Hours 10/2/2019 GP1.1 (Cleared Roofing Materials MP 54.0 WB Respd: 10/2/2019 14:22 N/A N/A 13:32:00 From Lanes) Actual: 0.83 Hours Regd: 10 Days 10/4/2019 GP12.1 MP 55.9 WB Respd: 10/4/2019 01:01 N/A N/A (Removed Graffiti) 08:00:00 Actual: 0.20 Days Regd: 6 Months 10/1/2019 Respd: 10/3/2019 00:30 ML6.1 MP 55.7 EB N/A N/A (Impact Damage) 16:45:00 Actual: 0.04 Months Reqd: 1 Hours Debris 10/3/2019 GP1.1 MP 43.0 WB Respd: 10/3/2019 13:44 N/A N/A (Cleared Broom From Lanes) 13:18:00 Actual: 0.43 Hours Debris Reqd: 1 Hours 10/18/2019 GP1.1 (Cleared Carcass From MP 50.4 WB Respd: 10/18/2019 12:00 N/A N/A 11:35:00 Lanes) Actual: 0.41 Hours Incident Response Read: 24 Hours 10/7/2019 ML13.1 (Accident Response For MP 55.9 EB Respd: 10/7/2019 04:00 N/A N/A 03:05:00 Gate Hit) Actual: 0.91 Hours Regd: 6 Months Guardrail 10/4/2019 GP5 1 MP 47 5 WB N/A N/A Respd: --(Impact Damage) 11:16:00 Actual: In Progress

All items were completed within the required response time. Items that are *In Progress* are still within the allowed response time.

F. Detailed Results of All Inspections, Assessments, and Testing Activities

During this reporting period there were no special inspections, assessments, or testing results outside normal operating condition.

G. Monthly Toll System Performance Reports

Toll system operated within proposed parameters per Ferrovial Services observations.

H. Preventative Maintenance Plan and Progress

Preventative Maintenance work is contingent on Initial Works Package implementation.

I, J. Mean Time between Failure (MTBF), Mean Time To Repair (MTTR)

No Maintained Elements experienced a failure type breakdown this month. Ferrovial Services considers a breakdown to be a failure when the element cannot be used for its intended purpose until repaired.