




Field surveys for wildlife, wetlands, and historic resources were conducted during the summer and fall of 2018. The map below depicts the results of this field work. Wetland boundaries were surveyed based on vegetation and hydrology; soils were not analyzed but will be confirmed prior to permitting and construction.

Selected wildlife information regarding camera locations/observations, lynx prey (snowshoe hare, squirrel) and other animal tracks, and other wildlife sightings are indicated on the map. Lynx are a threatened species in Colorado and the study area is within the Vail Pass Lynx Linkage Area, as identified by the US Forest Service. Surveying their primary prey in the corridor helps the wildlife experts determine/confirm the presence of suitable lynx habitat.

Historic resources, including the I-70 Vail Pass Historic District, have been surveyed and will be analyzed for impacts once all design options and the final alignment have been determined.



LEGEND

- | | | | |
|---------------|----------------------------------|---|--|
| Interstate 70 | Vail Recreation Trail | Lakes | Winter Tracks Observed |
| Roads | Mileposts | Elk Winter Range | Highest Number of Wildlife Tracks Observed |
| Creeks | I-70 Vail Pass Historic District | Example of Historic District Contributing Feature | Wildlife Cameras |
| Trails | Potential Wetlands | Native Cutthroat Areas | |






Field surveys for wildlife, wetlands, and historic resources were conducted during the summer and fall of 2018. The map below depicts the results of this field work. Wetland boundaries were surveyed based on vegetation and hydrology; soils were not analyzed but will be confirmed prior to permitting and construction.

Selected wildlife information regarding camera locations/observations, lynx prey (snowshoe hare, squirrel) and other animal tracks, and other wildlife sightings are indicated on the map. Lynx are a threatened species in Colorado and the study area is within the Vail Pass Lynx Linkage Area, as identified by the US Forest Service. Surveying their primary prey in the corridor helps the wildlife experts determine/confirm the presence of suitable lynx habitat.

Historic resources, including the I-70 Vail Pass Historic District, have been surveyed and will be analyzed for impacts once all design options and the final alignment have been determined.



LEGEND

- | | | | |
|---------------|----------------------------------|---|--|
| Interstate 70 | Vail Recreation Trail | Lakes | Winter Tracks Observed |
| Roads | Mileposts | Elk Winter Range | Highest Number of Wildlife Tracks Observed |
| Creeks | I-70 Vail Pass Historic District | Example of Historic District Contributing Feature | Wildlife Cameras |
| Trails | Potential Wetlands | Native Cutthroat Areas | |

