


GEOMETRY	GEOMETRIC FEATURES
PERFORMANCE MEASURES	LEVEL OF SERVICE (PM PEAK)
	ACCIDENT RATES
PEDESTRIAN	CONNECTIVITY
STRUCTURAL	STRUCTURES



GEOMETRIC FEATURES	GEOMETRY
LEVEL OF SERVICE (AM PEAK)	PERFORMANCE MEASURES
ACCIDENT RATES	
CONNECTIVITY	PEDESTRIAN
STRUCTURES	STRUCTURAL

- LEGEND**
- 0.00 TOTAL ACCIDENT RATE
 - B INTERSECTION LEVEL OF SERVICE
 - D MAINLINE LEVEL OF SERVICE
 - GOOD
 - FAIR
 - POOR
 - N/A
- BRIDGE RATING**
- (INDICATES) NEITHER FUNCTIONALLY OBSOLETE OR STRUCTURALLY DEFICIENT
 - (FDU), FUNCTIONALLY OBSOLETE UPPER
 - (SD) AND/OR (FDC), STRUCTURALLY DEFICIENT AND/OR FUNCTIONALLY OBSOLETE CLEARANCE

- LEGEND**
- 0.00 TOTAL ACCIDENT RATE
 - B INTERSECTION LEVEL OF SERVICE
 - D MAINLINE LEVEL OF SERVICE
 - GOOD
 - FAIR
 - POOR
 - N/A
- BRIDGE RATING**
- (INDICATES) NEITHER FUNCTIONALLY OBSOLETE OR STRUCTURALLY DEFICIENT
 - (FDU), FUNCTIONALLY OBSOLETE UPPER
 - (SD) AND/OR (FDC), STRUCTURALLY DEFICIENT AND/OR FUNCTIONALLY OBSOLETE CLEARANCE



EXISTING CONDITIONS - US 24 WEST CORRIDOR STUDY

DRAFT